



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21009575/Uvf3e2	
			Date: 27/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2186P		Veh. Inspected	SMP 870S
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2102728/SYH		Excess (\$)	0.00
Assign From	MELVIN YEE		Assign Date	13/09/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)		c.c	1317
Engine No.	HIDDEN		Year of Reg.	2019
Chassis No.	GK33423668		Colour	GREY
Odometer	72166 KM		Steering	AFFECTED
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		185/55 R16	DUNLOP	6 mm
L/H Front Tyre		185/55 R16	DUNLOP	6 mm
R/H Rear Tyre		185/55 R16	DUNLOP	6 mm
L/H Rear Tyre		185/55 R16	DUNLOP	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/09/2021		Inspection Date	13/09/2021
Survey held at	15 Kaki Bukit Road 4 Bartley Biz Centre #01-53			
Repairer	918 MOTORING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	