LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009585/VQF3E2

Date: 07/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070171875

Claimant Vehicle FBN2677L Insured Vehicle No : SGR17A

No:

Date of Loss: 10/09/2021 Nature of Claim: TP Claim No: 7754571140SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN2677L

Make & Model: YAMAHA FZN150, 149cc Engine No: G3E3E0031267

Reg. Date: 27/08/2018 (Man. Year: 2016) Chassis No: ME1RG1617G2001865

Colour: Red Odometer: 0 km

Engine Capacity: 149 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 130/60 R17
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/09/2021

BEAR GARAGE (HQ)

Date Inspected: 20/09/2021 Inspected At: 25 KAKI BUKIT ROAD 4 #03-62

Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$12,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
2	1	*FRONT WING MIRROR	Missing / Bent	0.00 F	*- F
3	1	*HANDLE BAR	Bent	0.00 F	*- F
4	1	*HANDLE BAR GRIP	Cut	0.00 F	*- F
5	1	*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
6	1	*HAND BRAKE LEVER	Scratched	0.00 F	*- F
F=Fra	anchise part.				
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >