

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721
Phone 8263 6295 (Steven) Fax 6266 2881

ESTIMATE

DATE 12-Oct-21
Vehicle No SJW5880D
Make/Model Mit. Lancer EX
Date of Accident 6-Sep-21

*Not Authorised
L1Ry 81500p
Penny After Paint
3 days*

Bill To:
ELLA BINTE SIDEK
c/o 176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721

NO	DESCRIPTION	AMOUNT
LIST ITEMS		
1	Rear bumper	\$ 731.00 ✓
2	Rear bumper side retainer x 2	\$ 36.00 X
3	Rear bumper centre beam	\$ 82.00 X
4	Rear bumper reinforcement 233	\$ 552.00 ✓
5	Rear bumper reflector x 2	\$ 52.00 X
6	Rear bumper tow hook cover	\$ 20.00 ✓
7	Rear bumper clips	\$ 48.00 ✓
8	Rear end panel	\$ 407.00 X
		1,928.00
Less 10%		192.80
		1,735.20
S/NETT ITEMS		
1	Reverse sensor	\$ 280.00 2000h
2	Rear number plate	\$ 30.00 X
3	Rear number plate holder	\$ 50.00 X
LABOUR & MISC		
1	Labour charge for panel beating and replace all damaged parts	\$ 600.00 300l
2	Spray painting on affected areas	\$ 600.00 400l
3	Apply anti-rust	\$ 60.00 X
4	To remove/refit reverse sensor	\$ 80.00 50l
5	Check wiring and lights	\$ 50.00 15h
		\$ 3,485.20
7% GST		243.96
		\$ 3,729.16

THIAM HENG HUAT PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: