

辉 阳 汽 车 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

11/09/2021

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLJ5074J

1pc	rear tailgate	953	B1	\$ 1,210.90	✓
1pc	rear tailgate "VEZEL" emble		me	\$ 55.10	✓
1pc	rear tailgate "HONDA" logo		su	\$ 58.50	X
1pc	rear tailgate "HYBRID" emble		me	\$ 65.20	—
1set	rear tailgate windscreen moulding		me	\$ 181.00	—
2pcs	rear tailgate reflector @\$381.50		wt su	\$ 763.00	X
1pc	rear tailgate inner lock		nd	\$ 198.40	✓
1pc	rear tailgate inner rubber		67-60sn nd/dig	\$ 135.20	508in
1pc	rear tailgate inner garnish	368.20	mycom	\$ 420.50	✓
2pcs	rear taillamp @\$485.50	0474.60	wt	\$ 971.00	✓
2pcs	rear side bumper @\$385.20	0195	ols	\$ 770.40	4
1pc	rear bumper	762.70	B1	\$ 986.30	✓
2pcs	rear bumper side retainer @\$24.80		su	\$ 49.60	X
1pc	rear end panel	415.60	B1	\$ 580.90	✓
1pc	rear end panel inner garnish	155	nd	\$ 250.20	✓
1pc	rear end panel inner sensor		su	\$ 188.50	X
1pc	rear end panel outer sensor		su	\$ 195.25	X
				\$ 7,079.95	
	less 20%			\$ 1,415.99	
				\$ 5,663.96	
1set	rear reverse sensor		s.nett	\$ 280.00	200sn
	remove & refix rear windscreen glass			\$ 120.00	✓
	wiring			\$ 80.00	201
	tuffkote			\$ 80.00	601
	sealant			\$ 80.00	405sn
	spray painting			\$ 1,000.00	7201
	labour charges			\$ 1,000.00	6001
	Total			\$ 8,303.96	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



A16
vch In
14/07/21

Not Authorised
11 Sep 84700h
Returning After Paint
5days