

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

11/09/2021

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLJ5074J

1pc	rear tailgate	Rs	\$ 1,210.90	✓
1pc	rear tailgate "VEZEL" emble	ms	\$ 55.10	✓
1pc	rear tailgate "HONDA" logo	sn	\$ 58.50	x
1pc	rear tailgate "HYBRID" emble	ms	\$ 65.20	✓
1set	rear tailgate windscreen moulding	ms	\$ 181.00	✓
2pcs	rear tailgate reflector @\$381.50	sn	\$ 763.00	x
1pc	rear tailgate inner lock	ms	\$ 198.40	✓
1pc	rear tailgate inner rubber	msl Dig	\$ 135.20	50% in
1pc	rear tailgate inner garnish		\$ 420.50	7
2pcs	rear taillamp @\$485.50	ms	\$ 971.00	✓
2pcs	rear side bumper @\$385.20	msl 7	\$ 770.40	
1pc	rear bumper	ms	\$ 986.30	✓
2pcs	rear bumper side retainer @\$24.80	sn	\$ 49.60	x
1pc	rear end panel		\$ 580.90	7
1pc	rear end panel inner garnish	msl	\$ 250.20	✓
1pc	rear end panel inner sensor		\$ 188.50	7
1pc	rear end panel outer sensor		\$ 195.25	7

less 20%

1set

rear reverse sensor

remove & refix rear windscreen glass

wiring

tuffkote

sealant

spray painting

labour charges

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 7,079.95

\$ 1,415.99

\$ 5,663.96

s.nett \$ 280.00 20% in

\$ 120.00 ✓

\$ 80.00 20%

\$ 80.00 60%

\$ 80.00 40% in

\$ 1,000.00 72%

\$ 1,000.00 60%

\$ 8,303.96

