

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0744/2021/JT
DATE : 13-Sep-21
WIP : 43991

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 15/9/21
YOUR INSURED VEH NO : SLB 7540 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR KRISTOFFER ELIAS DAVID MUNDEN
ADDRESS : 1 BALMORAL CRESCENT
#08-03 BALMORAL CREST
SINGAPORE 259882
TELEPHONE : HP +65 86083628
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5120461168
VEHICLE NO : **SMN 9260 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 31/8/2019
ENGINE NO : CHZ C32325
CHASSIS NO : WAUZZZ8V1KA114424
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Sep-21
PLACE OF ACCIDENT : INTERSECTION ORCHARD ROAD
AND PATTERSON ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 9260 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$	280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00 500	
3	TO RESPRAY REAR BUMPER.	\$	900.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,422.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 9260 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>reband</i>	1	\$ 1,944.00	✓
2	REAR BUMPER FIXING PARTS <i>3 pc</i>	1	\$ 193.00	+
3	REAR BUMPER ADAPTER	1	\$ 38.00	+
4	REAR BUMPER GUIDE SECTION - LH / RH <i>2 pc</i>	2	\$ 32.00	+
5	REAR BUMPER SPOILER <i>Not in</i>	1	\$ 237.00	+
6	REAR LIGHT REFLECTOR - LH <i>Not in</i>	1	\$ 41.00	+
7	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 603.00	?
8	REAR BUMPER BRACKET - LH / RH <i>Not in</i>	2	\$ 58.00	+
9	REAR PARKING AID SENSOR <i>Not in</i>	2	TBC	+
10	REAR PARKING AID SENSOR SEAL RING <i>Not in</i>	4	\$ 14.00	+
11	SUNDRIES <i>?</i>	1	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 3,460.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 5,882.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adam

SURVEYED DATE

: 15/09/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 03 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT