

...CLAIM SUBFOLDER...(Pending for Approval)**CLAIM SUBFOLDER TRACKING**

Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'd	Status
Main	09 Sep 2021 15:17	S\$7,925.50 Edit Estimates	09 Sep 2021 15:45 S\$ 7,925.50			Pending for Approval

Main

Reference

Claim Details

Documents

[Show All](#)**CLAIM SUBFOLDER DETAILS**

Insured:	NIL , ID : 0		
Main Claimant:	Heap Seng Group Pte Ltd		
Vehicle Reg. No.:	GBC5866X	Date of Loss :	03/09/2021 17:00 - :59 [101 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	0	Policy No. (Claimant):	
Repairer:	K Kim Hin Auto Pte Ltd (HQ)	PROFILE	160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		

ASSOCIATED MAIL RECEIVED[View All](#)[Compose Case Mail](#)

There are no mail for this case.



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
NIL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/09/2021
Vehicle Reg. No.:	GBC5866X	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	NISSAN URVAN, 3.0 5MT (A)	Vehicle Reg. Date:	21/03/2013
Vehicle Colour:	WHITE	Gen Condition:	EXCELLENT
Engine No:	ZD30298104K	Chassis No:	JN1MG4E25Z0796895
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Remarks:	CLAIM PUBLIC LIABILITY TOKIO MARINE.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS		Amount
Parts		5,014.50
Miscellaneous Items		11.00
Labour		2,900.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		7,925.50
+ GST 7.00% (S\$)		554.79
Nett Amount (S\$)		8,480.29

This claim is handled by: SANDRA KHONG YEE TENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 09 Sep 2021)**Parts:** N/A NISSAN URVAN 3.0 5MT (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBC5866X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON CONDENSER FAN MOTOR	0.00	0.00	*200.00 F
2	1		*AIR FILTER	0.00	0.00	*40.00 F
3	1		*ENGINE OIL FILTER	0.00	0.00	*20.00 F
4	2		*FRONT WHEEL BEARING (LH & RH)	0.00	0.00	*130.00 F
5	1		*FRONT BRAKE PAD	0.00	0.00	*115.00 F
6	1		*REAR BRAKE SHOE	0.00	0.00	*115.00 F
7	2		*REAR BRAKE PUMP (LH & RH)	0.00	0.00	*130.00 F
8	2		*REAR WHEEL BEARING (LH & RH)	0.00	0.00	*130.00 F
9	2		*REAR WHEEL BEARING OIL SEAL - INNER	0.00	0.00	*50.00 F
10	2		*REAR WHEEL BEARING OIL SEAL - OUTER	0.00	0.00	*50.00 F
11	1		*CLUTCH DISC	0.00	0.00	*175.00 F
12	1		*CLUTCH COVER	0.00	0.00	*290.00 F
13	1		*CLUTCH BEARING	0.00	0.00	*65.00 F
14	1		*ABS PUMP	0.00	0.00	*1,800.00 F
15	1		*ENGINE OIL (9 LIT)	0	0.00	*162.00 FS
16	1		*GEAR OIL (5 LIT)	0	0.00	*60.00 FS
17	1		*AXLE OIL (3 LIT)	0	0.00	*36.00 FS
18	1		*BRAKE OIL	0	0.00	*60.00 FS
19	1		*FRONT NUMBER PLATE	0	0.00	*40.00 FS
20	2		*FRONT DOOR COMPANY REGISTRATION STICKER	0	0.00	*50.00 FS
21	1		*REAR FLOOR PANEL TOP WOODEN BASE	0	0.00	*800.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$)	4,518.00
+ Margin on L,N Items 15.00% (\$)	496.50
Total Parts (\$)	5,014.50

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND WASH CARPET	New	450.00
2	TO REMOVE, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	600.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,200.00
4	LABOUR TO REMOVE AND REFIX GEAR BOX FOR RENEW CLUTCH DISC.	New	250.00
5	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY KING DOLLY AND WINCH OUT.	New	400.00
Gross Labour Cost (S\$)			2,900.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >