



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 5866X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	AIR CON CONDENSER FAN MOTOR (WCP)	SHORTED	200.00	200.00
1	AIR FILTER (WCP)	CONTAMINATED	40.00	40.00
1	ENGINE OIL FILTER (WCP)	CONTAMINATED	20.00	20.00
2	FRONT WHEEL BEARING (LH & RH) (WCP)	NOT NECESSARY	130.00	-
1	FRONT BRAKE PAD (WCP)	CONTAMINATED	115.00	115.00
1	REAR BRAKE SHOE (WCP)	CONTAMINATED	115.00	115.00
2	REAR BRAKE PUMP (LH & RH) (WCP)	CONTAMINATED	130.00	130.00
2	REAR WHEEL BEARING (LH & RH) (WCP)	SERVICEABLE	130.00	-
2	REAR WHEEL BEARING OIL SEAL - INNER (WCP)	NOT NECESSARY	50.00	-
2	REAR WHEEL BEARING OIL SEAL - OUTER (WCP)	NOT NECESSARY	50.00	-
1	CLUTCH DISC (WCP)	CONTAMINATED	175.00	175.00
1	CLUTCH COVER (WCP)	CONTAMINATED	290.00	290.00
1	CLUTCH BEARING (WCP)	CONTAMINATED	65.00	65.00
1	ABS PUMP (WCP)	CONTAMINATED	1,800.00	1,800.00
1	DIESEL FILTER (WCP)	NECESSARY	120.00	120.00
1	ECU UNIT (WCP)	CONTAMINATED	950.00	950.00
	COST PLUS 15%		657.00	603.00
			5,037.00	4,623.00
<u>SPECIAL NETT ITEMS</u>				
1	ENGINE OIL (9 LIT) (SN) (50%)	NECESSARY	162.00	81.00
1	GEAR OIL (5 LIT) (SN) (50%)	NECESSARY	60.00	30.00
1	AXLE OIL (3 LIT) (SN)	NECESSARY	36.00	36.00
1	BRAKE OIL (SN) (50%)	NECESSARY	60.00	30.00
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	40.00	-
2	FRONT DOOR COMPANY REGISTRATION STICKER (SN)	NOT NECESSARY	50.00	-
1	REAR FLOOR PANEL TOP WOODEN BASE (SN)	CONTAMINATED	800.00	800.00
			1,208.00	977.00
<u>LABOUR</u>				
	TO REMOVE AND WASH CARPET.		450.00	300.00

Report Ref No. CS/SGK21009610/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		600.00	150.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,200.00	1,000.00
	LABOUR TO REMOVE AND REFIX GEAR BOX FOR RENEW CLUTCH DISC.	NOT NECESSARY	250.00	-
	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY KING DOLLY AND WINCH OUT.		400.00	300.00
	OD / TP CASE (INSURER).	NOT NECESSARY	11.00	-
	TO CONDUCT PROGRAMMING.		380.00	380.00
			3,291.00	2,130.00
GRAND TOTAL			9,536.00	7,730.00
RECOMMENDED COST OF REPAIRS				7,730.00

Report Ref No. CS/SGK21009610/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.