

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/09/2021

TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK

Date: 14 Sep 2021

Policy No: 5115943957-01 PREMIUM

Veh Reg No: SLQ2034H

Make/Model: HONDA VEZEL

Chassis No: RU31245325

Engine No: LEB5945347

Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	801.20	1 PC	77 801.20	
2 FRONT BUMPER REINFORCEMENT	321.40	1 PC	B1 321.40	
3 FRONT BUMPER CENTRE LOWER GRILLE	77.40	1 PC	CM 77.40	
4 FRONT BUMPER TOW HOOK COVER	27.10	1 PC	MT 27.10	
5 FRONT BUMPER FOG LAMP GARNISH	45.20	2 PC	D11 90.40	
6 FRONT BUMPER RH FOG LAMP	327.70	1 PC	B1 327.70	
7 FRONT BUMPER RH FOG LAMP HOLDER	51.30	1 PC	CM 51.30	
8 FRONT BUMPER SIDE RETAINER	20.60	2 PC	CM 41.20	
9 FRONT BUMPER CLIP	3.50	6 PC	AC 21.00	
10 FRONT BUMPER LOWER SPOILER	381.20	1 PC	D11 381.20	
11 BONNET	892.40	1 PC	B1 892.40	
12 BONNET HINGE	45.80	2 PC	D11 91.60	
13 BONNET INNER LOCK	98.20	1 PC	B1 98.20	
14 BONNET INSULATOR	122.90	1 PC	T1 122.90	
15 BONNET CLIP	3.50	6 PC	AC 21.00	
16 BONNET RH INNER RUBBER	37.50	1 PC	LT 37.50	
17 FRONT GRILLE HOUSING	351.80	1 PC	CM 351.80	
18 FRONT GRILLE OUTER GARNISH	421.90	1 PC	CM 421.90	
19 FRONT GRILLE CHROME MOULDING	95.20	1 PC	AC 95.20	
20 FRONT GRILLE LOGO	24.70	1 PC	MT 24.70	
21 FRONT GRILLE CENTRE BRACKET	38.70	1 PC	B1 38.70	
22 FRONT GRILLE SIDE BRACKETS	17.60	2 PC	CM 35.20	
23 HEADLAMP	1,794.20	2 PC	3,588.40	
24 HEADLAMP LOWER BRACKET	35.40	2 PC	CM 70.80	
25 HORN RH	39.70	1 PC	MT 39.70	
26 FUSE BOX ASSY	980.70	1 PC	CM 980.70	
27 FRONT FENDER	558.70	2 PC	1,117.40	
28 FRONT FENDER EMBLEM	58.70	2 PC	117.40	
29 FRONT FENDER INNER SHIELD	136.90	2 PC	273.80	
30 FRONT FENDER INNER SHIELD CLIP	3.50	12 PC	42.00	
31 FRONT FENDER WHEEL ARCH GARNISH	195.20	2 PC	390.40	
32 FRONT RH FENDER EXTENSION ARM	120.70	1 PC	120.70	
33 FRONT RH FENDER INNER CENTRE ARM	50.40	1 PC	50.40	
34 FRONT RH FENDER OUTER CENTRE ARM	76.20	1 PC	76.20	
35 FRONT RH FENDER INNER PANEL	115.20	1 PC	115.20	
36 FRONT RH WHEEL HOUSING	406.20	1 PC	406.20	
37 FRT SUPPORT PANEL	578.20	1 PC	578.20	
38 FRONT SUPPORT PANEL INNER TOP GARNISH	85.90	1 PC	85.90	

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 12/09/2021
 TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK
 Date: 14 Sep 2021
 Policy No: 5115943957-01 PREMIUM
 Veh Reg No: SLQ2034H
 Make/Model: HONDA VEZEL
 Chassis No: RU31245325
 Engine No: LEB5945347
 Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
39 FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	3.50	6 PC	21.00	✓
40 RADAR SENSOR ASSY BRACKET	580.70	1 PC	580.70	✓
41 RADAR SENSOR ASSY	2,850.70	1 PC	2,850.70	?
42 ABS PUMP ASSY	2,738.90	1 PC	2,738.90	✓
43 WIPER WASHER TANK	75.20	1 PC	75.20	✓
44 WIPER WASHER NECK	28.30	1 PC	28.30	✓
45 WIPER WASHER MOTOR	89.20	1 PC	89.20	✓
46 FRONT WIPER PANEL GARNISH	240.70	1 PC	240.70	✓
47 FRT LOWER CENTRE UNDER COVER	96.80	1 PC	96.80	✓
48 AIR-CON CONDENSER	750.20	1 PC	750.20	?
49 RADIATOR	1,376.20	1 PC	1,376.20	?
50 RADIATOR RH SIDE GARNISH	30.40	1 PC	30.40	✓
51 RH ENGINE MOUNTING	184.90	1 PC	184.90	?
52 ENGINE LH MOUNTING	335.20	1 PC	335.20	?
53 SPORT RIM	765.90	4 PC	3,063.60	✓
54 FRONT RH DOOR	956.20	1 PC	956.20	✓
55 FRONT RH DOOR FRAME STICKER	25.70	1 PC	25.70	✓
56 FRONT RH DOOR CHECKER	59.20	1 PC	59.20	✓
57 FRONT RH DOOR TOP HINGE	45.20	1 PC	45.20	✓
58 FRONT RH DOOR BOTTOM HINGE	59.20	1 PC	59.20	✓
59 FRONT RH DOOR SPEAKER	120.70	1 PC	120.70	?
60 FRONT RH DOOR POWER WINDOW MOTOR & REGULATOR	400.70	1 PC	400.70	✓
61 FRONT RH DOOR WIRE HARNESS	590.00	1 PC	590.00	?
62 FRONT RH DOOR INNER LOCK	262.90	1 PC	262.90	?
63 REAR RH DOOR	930.20	1 PC	930.20	✓
64 REAR RH DOOR FRAME STICKER	28.30	1 PC	28.30	✓
65 REAR RH DOOR INNER LOCK	220.90	1 PC	220.90	X
66 REAR RH DOOR TOP HINGE	40.10	1 PC	40.10	?
67 REAR RH DOOR BOTTOM HINGE	40.10	1 PC	40.10	✓
68 REAR RH DOOR CHECKER	55.90	1 PC	55.90	?
69 REAR RH DOOR POWER WINDOW MOTOR & REGULATOR	378.90	1 PC	378.90	?
70 RH B PILLAR	725.40	1 PC	725.40	✓
71 REAR RH WHEEL ARCP GARNISH	195.20	1 PC	195.20	✓
72 FRONT WINDSCREEN GLASS MOULDING	207.40	1 PC	207.40	✓
73 FRONT AIRBAG SENSOR	250.40	1 PC	250.40	✓
74 AIR BAG ECU	980.90	1 PC	980.90	✓
75 DASHBOARD ASSY	800.60	1 PC	800.60	✓
76 PASSENGER FRT AIR BAG	2,236.70	1 PC	2,236.70	✓
77 STEERING AIRBAG	1,605.90	1 PC	1,605.90	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 12/09/2021
TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK
Date: 14 Sep 2021
Policy No: 5115943957-01 PREMIUM
Veh Reg No: SLQ2034H
Make/Model: HONDA VEZEL
Chassis No: RU31245325
Engine No: LEB5945347
Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
78 STEERING SPIRAL CABLE	389.20	1 PC	<i>Me</i> 389.20	<i>✓</i>
79 FRONT SEAT BELT	789.70	2 PC	<i>Ta</i> 1,579.40	<i>✓</i>
80 FRONT SEAT BELT LOWER CENTRE GARNISH	129.40	2 PC	258.80	<i>7</i>
81 SIDE AIR BAG	860.20	2 PC	<i>Burn</i> 1,720.40	<i>✓</i>
82 ROOF LINING	1,250.70	1 PC	<i>Ta</i> 1,250.70	<i>✓</i>
83 FRONT RH SEAT AIRBAG	850.00	1 PC	<i>Burn</i> 850.00	<i>✓</i>
84 FRONT RH SHOCK ABSORBER	430.20	1 PC	<i>Ry</i> 430.20	<i>✓</i>
85 FRONT RH TOP MOUNTING	29.70	1 PC	<i>Ry</i> 29.70	<i>✓</i>
86 FRONT RH LOWER ARM	350.70	1 PC	<i>Ry</i> 350.70	<i>✓</i>
87 FRONT RH BALL JOINT	98.70	1 PC	<i>Ry</i> 98.70	<i>✓</i>
88 FRONT RH KNUCKLE ARM	259.70	1 PC	<i>Ry</i> 259.70	<i>✓</i>
89 FRONT RH WHEEL HUB	187.20	1 PC	<i>Ry</i> 187.20	<i>✓</i>
90 FRONT RH WHEEL HUB BEARING	138.50	1 PC	<i>Me</i> 138.50	<i>✓</i>
91 FRONT RH DRIVESHAFT	1,100.20	1 PC	1,100.20	<i>7</i>
92 FRONT RH STAY LINKAGE	60.40	1 PC	60.40	<i>7</i>
93 FRONT CROSSMEMBER	795.20	1 PC	795.20	<i>7</i>
94 STEERING RACK ASSY	1,172.90	1 PC	1,172.90	<i>7</i>
95 STEERING RH TIE ROD END	71.80	1 PC	71.80	<i>7</i>
			46,846.80	
		Less 20%	9,369.36	37,477.44
Special Net				
96 FRONT NUMBER PLATE	35.00	1 PC	<i>Me</i> 35.00	<i>✓</i>
97 COOLANT	40.00	1 PC	<i>Me</i> 40.00	<i>✓</i>
98 FRONT WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>Me</i> 40.00	<i>✓</i>
99 SIDE SKIRT	350.00	1 SET	<i>Me</i> 350.00	<i>✓</i>
100 FRONT RH TYRE	180.00	1 PC	<i>Me</i> 180.00	<i>30.00</i>
101 BRAKE FLUID 2 LITRES	20.00	1 PC	<i>Me</i> 20.00	<i>✓</i>
			665.00	665.00
Labour				
102 TOWING (CRANE/WINCH UP)	170.00	1 LA	170.00	<i>✓</i>
103 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	<i>✓</i>
104 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	<i>✓</i>

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 12/09/2021
 TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK
 Date: 14 Sep 2021
 Policy No: 5115943957-01 PREMIUM
 Veh Reg No: SLQ2034H
 Make/Model: HONDA VEZEL
 Chassis No: RU31245325
 Engine No: LEB5945347
 Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
105 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,BOTH FENDERS,HEADLAMPS,BOTH RH DOORS & ATTACHMENTS;TO CUT,WELD & RENEW FRT SUPPORT PANEL,FRT RH WHEEL HOUSING,RH B-PILLAR;KNOCKING & REPAIR FRT RH A PILLAR,RH ROCKER PANEL & REALIGN SAME	2,200.00	1 LA	2,200.00	2000/-
106 PUTTY & RESPRAY FRT BUMPER,LOWER SPOILER,BONNET,BOTH FENDERS,BOTH RH DOORS,REAR RH SIDE BUMPER,REAR RH FENDER,FRT SUPPORT PANEL,RH B PILLAR,RH ROCKER PANEL,BOTH RH WHEEL ARCH GARNISHS,FRT LH WHEEL ARCP GARNISH & ALL AFFECTED AREAS	2,000.00	1 LA	2,000.00	1900/-
107 REMOVE & REFIX BOTH RH DOORS,WINDOW GLASSES & RESET CENTRAL LOCKINGS	120.00	1 LA	120.00	✓
108 REMOVE & REFIX DASHBOARD ASSY TO FACILIATE REPAIR	250.00	1 LA	250.00	✓
109 REMOVE & REFIX FRT SEATS,ROOF LINING,CARPET TO FACILITATE REPAIR	180.00	1 LA	180.00	150/-
110 REMOVE & REFIX FRT SEAT BELTS,AIRBAG ECU,STEERING AIRBAG,PASSENGER AIRBAG & REALIGN THE SAME	250.00	1 LA	250.00	200/-
111 REMOVE & REFIX AIRBAG ECU,REPROGRAMME & RESET FAULT CODE	200.00	1 LA	200.00	✓
112 REMOVE & REFIX ENGINE MOUNTINGS,FRT RH UNDERCARRIAGE,STEERING RACK ASSY,DRIVESHAFT,CROSSMEMBER & REALIGN THE SAME	350.00	1 LA	350.00	?
113 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	✓
114 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	?
115 REMOVE & REFIX SPORT RIMS X4, TYRES,BALANCE & REALIGN THE SAME	160.00	1 LA	160.00	120/-
116 REMOVE & REFIX ABS PUMP ASSY & BLEED BRAKE SYSTEM	180.00	1 LA	180.00	120/-
117 RUSTPROOFING	180.00	1 LA	180.00	✓
118 TO APPLICATION,BREAK AND RESEAL FRT NUMBER PLATE (OPC) , RESEAL & EDAY LICENCE	80.00	1 LA	80.00	✓
119 REMOVE & REFIX RADAR SYSTEM & CALIBRATE	200.00	1 LA	200.00	150/-
			7,070.00	7,070.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company