



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG21009614/R1tf3e2	
			Date: 10/11/2021	
			Code: MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	PUBLIC LIABILITY	<b>Veh. Inspected</b>	SLP 2942S
	<b>Policy No.</b>	B 300445396 CAR	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	261912 CAR	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	MARVIN CHIA	<b>Assign Date</b>	14/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	SSANGYONG TIVOLI XLV 1.6D	<b>c.c</b>	1597
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
	<b>Chassis No.</b>	KPT36B1USHP145394	<b>Colour</b>	RED
	<b>Odometer</b>	126365 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	205/60 R16	ARIVO	6 mm
	<b>L/H Front Tyre</b>	205/60 R16	ARIVO	6 mm
	<b>R/H Rear Tyre</b>	205/60 R16	ARIVO	6 mm
	<b>L/H Rear Tyre</b>	205/60 R16	ARIVO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	27/08/2021	<b>Inspection Date</b>	14/09/2021
	<b>Survey held at</b>	2A Woodlands Industrial Park D Street 2		
	<b>Repairer</b>	-		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	