

	Description	Part Number	Part Source	Price SGD
71 /	BONNET <i>lt</i>	60100T8NT00ZZ	Original	450.00 /
002 /	<i>ne</i> BONNET INSUL CLIPX10	BONNETINSULATOR	Original	20.00 /
0492	BONNET LOCK <i>Xsu</i>	74120T7WA01	Original	75.00 /
4465 /	CONDENSER <i>photo</i>	80110T7A003	Original	370.00 /
0283 /	FRONT BUMPER <i>de</i>	71101T8NT00ZZ	Original	370.00 /
1009	FRONT PANEL CPL <i>Xsu</i>	60400T8NT50ZZ	Original	400.00 /
0391 /	FRONT SPOILER <i>sea</i>	71110T7A000	Original	140.00 /
1000 /	<i>ne</i> FRT BUMPER CLIP X 10	FRT BUMPER CLIP	Original	20.00 /
0340 /	<i>on</i> FRT BUMPER SUPPORT <i>?</i>	71130T8NT00ZZ	Original	180.00 /
0300 /	<i>sea</i> FRT TOWING EYE COVER	71104T7A000ZR	Original	12.00 /
0410 /	GRILLE <i>cre</i>	71121T8NT50	Original	210.00 /
0431 /	GRILLE BADGE <i>MS</i>	75700TA0A00	Original	18.00 /
1001 /	GRILLE CVR CLIP X 10 <i>ne</i>	GRILLE CVR CLIP	Original	20.00 /
0475 /	L/BONNET HINGE <i>lt</i>	60170T8NT01ZZ	Original	33.00 /
0511 /	L/BONNET SEAL <i>ne</i>	74192T7JH00	Original	15.00 /
0513 /	L/BONNET SEAL <i>ne</i>	74128T7JH00	Original	15.00 /
0343	L/BUMPER CORNER <i>Xsu</i>	71190T7A000	Original	12.00 /
	BRKT			
0345	L/F AIR DUCT <i>Xsu</i>	71116T8NT50	Original	30.00 /
0561	L/F HEADLAMP CPL <i>Xsu</i>	33150T7SE51	Original	985.00 /
0319 /	L/F UPP BUMPER BRKT <i>on</i>	71198T7AJ00	Original	12.00 /
0435 /	L/GRILLE TRIM <i>on</i>	71128T8NT00	Original	50.00 /
0415 /	<i>nec</i> L/RAD-GRILLE BRACKET <i>?</i>	71152T7A000	Original	24.00 /
7751	<i>Xsu</i> L/UPP RADIATOR BRKT	74176T7A000	Original	10.00 /
0787 /	<i>ad</i> L/WING MOULDING <i>on</i>	74157T7MH01	Original	55.00 /
0351 /	LOWER FRONT GRILLE <i>on</i>	71103T7JH00	Original	55.00 /
0476 /	R/BONNET HINGE <i>lt</i>	60120T8NT01ZZ	Original	33.00 /
0514 /	R/BONNET SEAL <i>ne</i>	74121T7JH00	Original	15.00 /
0512 /	R/BOONET SEAL <i>ne</i>	74142T7JH00	Original	15.00 /
0344 /	<i>on</i> R/BUMPER CORNER <i>?</i>	71140T7A000	Original	12.00 /
	BRKT			
0346 /	R/F AIR DUCT <i>de</i>	71111T8NT50	Original	30.00 /
0562 /	R/F HEADLAMP CPL <i>on</i>	33100T7SE51	Original	985.00 /
0320 /	R/F UPP BUMPER-BRKT <i>on</i>	71193T7AJ00	Original	12.00 /
0416 /	<i>on</i> R/RAD-GRILLE BRACKET <i>?</i>	71151T7JH00	Original	24.00 /
7752	<i>Xsu</i> R/UPP RADIATOR BRKT	74171T7AJ00	Original	10.00 /
0788 /	<i>on</i> R/WING MOULDING	74107T7MH01	Original	55.00 /
1003	RADAR	RADARMILLIMETER	Original	2,160.00 /
	MILLIMETERWAVE <i>Xsu</i>			
1004	RADAR WAVE BRACKET <i>on</i>	RADAR BRACKET	Original	450.00 /
0413 /	<i>on</i> RAD GRILLE BRACKET <i>on</i>	71150T7JH00	Original	24.00 /
0424 /	RAD GRILLE COVER <i>on</i>	71121T8NP50	Original	170.00 /
7761 /	RADIATOR <i>photo</i>	1901050T902	Original	865.00 /
0411 /	<i>on</i> UP/CVR RADIAT GRILLE <i>?</i>	71129T7MH00	Original	50.00 /
1436	<i>Xsu</i> WASHER RESERVOIR <i>?</i>	76841T8NT01	Original	60.00 /

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Addition(+10.00%)

Total

4359
0.00
8,551.00
855.10

9,406.10

Extras

Code	Description	Price SGD
------	-------------	-----------

	Description	Price SGD
05	FRONT LICENSE PLATE LICENSE PLATE	35.00*
06	4 LITRES COOLANT COOLANT 4L	35.00*
007	REFILL A/C GAS REFILL A/C GAS	80.00*
1008	CHECK/RECTIFY WIRING CHECK WIRING	20.00*
1009	CHECK/SYNC FRT RADAR SYNC FRT RADAR	150.00*
	Total Extras	320.00

Final Calculation

	SGD	SGD
Parts	8,551.00	
Addition(+10.00%)	855.10	
Total Parts		9,406.10
Labour Time Base 10 WU/h		
Total 133.0 WU X 50.00 SGD/h	665.00	620
Total of Labour		665.00
Total Of Extras		320.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 50.00 SGD/h	500.00	✓
Material Cost	215.87	✓
Total Paint Including Material		715.87
Repair Cost Excludes GST		11,106.97
GST (+7.00%)		777.49
Repair Cost Included GST		11,884.46
Deductions (Excludes GST)	-500.00	
Deduction For Excess		-500.00
Total Of Deductions (Excludes GST)		10,606.97
Grand Total Excludes GST		742.49
GST (+7.00%)		11,349.46
Grand Total Included GST		

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Pass
Hp 90010068
5 days
P/P
14/09/21 @ 14/10

REVERT

EXCESS: 500

Resy before paint