

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 738356
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/09/2021
User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$530.00			265				
Total Labour		\$530.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$616.00			446				
Total Spray Painting & Panel Beating		\$616.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010298	VE	88-25225-8039	LAMP STOP LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	ca
Total					\$1,141.70		\$1,027.53		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

711

1027.53
711.00

1738.53
20%
1390.82

4/5 - \$1400

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068
2 days
4/5
13/09/21 @ 1535
Reg after repair