

REF: Tm1/21009623/Ky

ASSIGNMENT

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD364J

AAD2109-021

Not Authorized
11 Sep @ 2250h

Vehicle No.:
Chassis No.:
Vehicle Make: 13 SEP 2021
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD364J
VF1ABL15AUC282738
RENAULT
LATITUDE
03/09/2021
Tokio.
17/05/2016

PART	LIST
1 BUMPER COVER FRT	\$ Bu 747.20 ✓
1 BUMPER ABSORBER FRT	\$ In 394.68 X
1 BUMPER BEAM FRT	\$ In 663.70 X
1 BUMPER BRACKET KIT FRT RH	\$ DII 101.40 —
1 HEADLAMP RH	\$ m3 cm 743.60 —
1 WIPER RESERVOIR	\$ In 179.60 X
1 FENDER PANEL FRT RH	\$ Bu 437.10 ✓
1 WHEELARCH FRT RH	\$ In 191.40 X
	\$ 3,267.28
10%	\$ 326.73
	\$ 2,940.55

Special Nett

1SET BUMPER BRACKET CTR CLIP	\$ In 33.00 ✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ In 10.00 X
1SET BUMPER RETAINER RH CLIP RR	\$ In 20.00 ✓
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ In 10.00 X
1SET BUMPER RETAINER CLIP LH RR	\$ In 20.00 X
1 BUMPER CLIP FRT	\$ In 85.00 665m
1 FENDER CLIP	\$ In 65.00 X
1 FENDER LINER CLIP	\$ In 60.00 X

TOTAL \$ 303.00
TOTAL PARTS \$ 3,243.55

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 440h

Tm1 / 21009623/K4

ASSIGNMENT

C

Faster memory speed
Precision touchpad
Intel® Celeron® processor N4020
Intel® UHD Graphics

AIG
veh In
D

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD364J

AAD2109-021

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	400/-
To Rust-Proofing Of The Affected Areas.	\$	170.00	30/-
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/-

TOTAL \$ 7,580.00

Over All Total \$ 13,764.10

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(LUMP SUM)

Repair Days

10 DAYS
2 days

Acknowledged by Repairer

Signature:

Date: