



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile **CS3/CTI21007470/Guc-1**

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: ~~CS3/CTI21007470/Guc-1~~

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date: ~~08/07/2021~~ 14.09.2021

Code: CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YN 1883S	Veh. Inspected	GBB 2941L
Policy No.	DMCVSNW00048152100	Coverage (\$)	0.00
Claim No.	SNM21D203782/C02/YN1883S/LEEPG	Excess (\$)	0.00
Assign From	CECILIA LEE PENG GEOK	Assign Date	08/07/2021 14.09.2021

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/07/2021	Inspection Date	08/07/2021
Survey held at	AUTO BEST MOTOR SERVICES BLK 3006 UBI ROAD 1 #01-362 SINGAPORE 408700		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--