

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En A	Automo	bile CS3/CT	121007470/ G uc
	CHINA TAIPING IN	F	Ref: '	000/0TI21007	'470/Que	
	3 ANSON ROAD # SPRINGLEAF TOV	[Date: •	09/07/2021	14.09.2021	
			(Code:	СТІ	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 1883S	Veh. Inspected		GBB 2941L	
	Policy No.	DMCVSNW00048152100	Coverage (\$)		0.00	
	Claim No.	SNM21D203782/C02/YN1883S/ LEEPG	Excess (\$)		0.00	
	Assign From	CECILIA LEE PENG GEOK	Assign Date		08/07/2021	14.09.2021
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
5.	General Information					
	Accident Date	06/07/2021	Inspection Date	!	08/07/2021	
	Survey held at	AUTO BEST MOTOR SERVICES	5			
		BLK 3006 UBI ROAD 1 #01-362 SINGAPORE 408700				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

24.09.2021 3.51pm Hi LKK We have confirmed settlement with third party. Please close file at your end. Thank you. - Cecilia Lee

Celine 27.09.2021