

CB 7742A 2016 April

TTCNB.

Toyota Hiace 2982 CC

Asher

KDH 2010175255

Reer Bumper Dehind 582.50 ✓
Reer Bumper Clips ^{new} 30(SN) ✓
Reer Bumper Side Holder x02 ^{new} 59.8 x2 = 119.60 ✓
Reer Bumper Reinforcement ^{MP} 366.10 ✓
Reverse Sensor ^{Damaged} 280(SN) 200(SN) ✓

List: 58250

S.N: 230

Item 25%: 436.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel Beating

~~500~~ 300

Spray Painting.

~~500~~ 200

Wiring

50 x 550

To remove reverse sensor

~~100~~ 50

total: 1216.87 ✓
w/s: 950 ✓
02 Days.