



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
(UEN 53311047E)

LKK Auto Consultants Pte Ltd

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Tax Invoice : 202110-089

Date : 18/10/2021

Vehicle No. : CB7742A

Make Model : TOYOTA HIACE 3.0 DX DIESEL TURBO AT 2WD, 2982C


Accident Location/Date: 07/09/2021 15:50 (SGT), BUANGKOK DRIVE

PARTICULAR	AMOUNT
Cost of Repairs & Labor	\$. 950.00
Loss of Use, 02 Days X @\$200.00 per day	\$. 400.00
Pre-Repair Inspection, 02 Days x @\$200.00 per day	\$. 400.00

Singapore Dollars: One Thousand Seven Hundred Fifty Only

Total S\$: 1,750.00

=====



YSK Auto Workshop