

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807		Ref: CS/MSG21009630/Duf3 Date: 14/09/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 5816D	Veh. Inspected	SH 7191T
Policy No.	29152864	Coverage (\$)	0.00
Claim No.	637939	Excess (\$)	0.00
Assign From	MERIMEN (ELAINEN GU SIAU MEI)	Assign Date	14/09/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/09/2021	Inspection Date	14/09/2021
Survey held at	Blk 9 Sector C, #01-42 Sin Ming		
Repairer	BIFROST AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

14.09.2021 4.54pm Received email from Crystal Lee, due to insured special request.

They will cancel the survey assignment in Merimen.

Celine 30/11/2021