



AIG Asia Pacific Insurance Pte. Ltd.

AIG Building
78 Shenton Way #07-16
Singapore 079120
T : (65) 6419 3000
www.aig.sg

Claim No: 6696542745SG **Date of Survey:** 01/09/2021
Repairer: LAI HUAT (MENG KEE) MOTOR PTE LTD

REFERENCE

Insured: ONG LAY HAR **Policy No:** 2100461203-05
Date of Loss: 27/08/2021 **Nature of Claim:** OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SGU9067E
Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) **Reg. Date:** 19/04/2016
Engine No: 4A92CG8070 **Chassis No:** JMYSRCY1AGU004106

CONDITION OF TYRES

Front Tyre Size:	205 60 R16	Rear Tyre Size:	205 60 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No		
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes	Pre-accident Condition:	

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	1,223.20	1,223.20	0.00	0.00
Miscellaneous Items	466.00	461.00	5.00	1.07
Labour	480.00	480.00	0.00	0.00
Paintwork Labour	1,788.16	1,788.16	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	3,957.36	3,952.36	5.00	0.13
- Excess (\$)	600.00	600.00	0.00	0.00
(S\$)	3,357.36	3,352.36	5.00	0.15
+ GST 7.00/7.00% (S\$)	235.02	234.67	0.35	0.15
Nett Amount (S\$)	3,592.38	3,587.03	5.35	0.15

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 10.0 days

Authorised Repair : Yes

Inspection conducted by : Pakianathan, Henry (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/FASTENING CLIP		9.00 F	*9.00 F
2	1	NA	*L/F DOOR WINDOW		135.00 F	*135.00 F
3	1	NA	*L/F WING TOP 1/4 CVR		16.00 F	*16.00 F
4	1	NA	*LWR W-SCREEN MLDG		38.00 F	*38.00 F
5	1	NA	*R/FASTENING CLIP		9.00 F	*9.00 F
6	1	NA	*REAR BADGE		25.00 F	*25.00 F
7	1	NA	*REAR MODEL BADGE		25.00 F	*25.00 F
8	1	NA	*REAR SCREEN		350.00 F	*350.00 F
9	1	NA	*UPP WINDSCREEN MLDG		55.00 F	*55.00 F
10	1	NA	*WINDSCREEN		450.00 F	*450.00 F

F=Franchise part.

Sub Total (\$)	1,112.00	1,112.00
+ Margin on L,N Items 10.00/10.00% (\$)	111.20	111.20
Total Parts (\$)	1,223.20	1,223.20

AIG Asia Pacific Insurance Pte. Ltd./SGU9067E/20/09/2021 12:05

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT WINDSCREEN SOLAR FILM	150.00	150.00
2	1	FRT W/S SEALANT	40.00	40.00
3	1	IU BRACKET	15.00	10.00
4	1	L/F DOOR WINDSCREEN SOLAR FILM	60.00	60.00
5	1	REAR WINDSCREEN SOLAR FILM	150.00	150.00
6	1	RR W/S SEALANT	40.00	40.00
7	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			466.00	461.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	1,320.00	1,320.00
2	Total Paint Materials	New	468.16	468.16
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	480.00	480.00
Gross Labour Cost (\$\$)			2,268.16	2,268.16

AIG Asia Pacific Insurance Pte. Ltd./SGU9067E/20/09/2021 12:05

< END OF REPORT >