



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009638/Auf3e2	
			Date: 07/10/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 1772T	Veh. Inspected	SDG 8225G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/09/21/2024	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	14/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	LEXUS RX270	c.c	2672	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JTJZA11A502426057	Colour	SILVER	
Odometer	286756 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	MICHELIN	6 mm	
L/H Front Tyre	235/60 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/60 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/60 R18	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/09/2021	Inspection Date	15/09/2021	
Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>6 Working Days</b>	