



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: MS FIRST CAPITAL INSURANCE CLAIMS DEPARTMENT
COMPANY NAME: MS FIRST CAPITAL INSURANCE
STREET ADDRESS: 36, Robinson Road, #16-01, City House
POSTAL CODE: 068877
PHONE: (65) 6507 3848

DATE: 14/9/2021

REF: SDG8225G
VEHICLE NO.: SDG8225G
MAKE: LEXUS
MODEL: RX270
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>LABOUR</u>						
1	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELL IN PLACE NEW PANELS WITH FULL ALIGNMENT	1		\$1,500.00	\$ 1,500.00		\$ 1,500.00
2	TO PROVIDE SKILL LABOUR AND MATERIAL TO PREPARE AND PAINT ALL NEW PART AND PANELS	1		\$1,200.00	\$ 1,200.00		\$ 1,200.00
3	TO USE CHASSIS ALIGNMENT EQUIPMENT. TO REALIGN BACK REAR LH CHASSIS	1		\$750.00	\$ 750.00		\$ 750.00
4	TO REMOVE AND REFIX AND REPLACE EXHAUST PIPE WITH FULL ALIGNMENT	1		\$200.00	\$ 200.00		\$ 200.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	1		\$160.00	\$ 160.00		\$ 160.00
6	TO REMOVE AND REFIX ALL REAR WIRING AND REPLACE REVERSE SENSOR	1		\$200.00	\$ 200.00		\$ 200.00
7	TO DO ELECTRICAL 4 WHEEL ALIGNMENT	1		\$200.00	\$ 200.00		\$ 200.00
	<u>PARTS</u>						
1	REAR BUMPER	1		\$960.30	\$ 960.30		\$ 960.30
2	REAR BUMPER CLIPS	10		\$5.50	\$ 55.00		\$ 55.00
3	REAR BUMPER REFLECTOR LH & RH	2		\$282.60	\$ 565.20		\$ 565.20
4	REAR BUMPER SIDE RETAINER BIG LH & RH	2		\$125.40	\$ 250.80		\$ 250.80
5	REAR BUMPER SIDE RETAINER SMALL LH & RH	2		\$116.50	\$ 233.00		\$ 233.00
6	REAR BUMPER REINFORCEMENT	1		\$738.10	\$ 738.10		\$ 738.10
7	REAR BUMPER SPONGE	1		\$173.10	\$ 173.10		\$ 173.10
8	REVERSE SENSOR 4 PCS	4		\$392.80	\$ 1,571.20		\$ 1,571.20
9	REAR END PANEL	1		\$918.50	\$ 918.50		\$ 918.50
10	REAR SPARE TYRE HOUSING	1		\$991.70	\$ 991.70		\$ 991.70
11	REAR UNDER COVER LH SIDE	1		\$699.70	\$ 699.70		\$ 699.70
12	REAR UNDER COVER LH SIDE CLIPS	10		\$10.80	\$ 108.00		\$ 108.00
13	REAR UNDER COVER RH SIDE	1		\$418.50	\$ 418.50		\$ 418.50
14	REAR UNDER COVER RH SIDE CLIPS	5		\$10.80	\$ 54.00		\$ 54.00
15	REAR LEFT CHASSIS	1		\$1,580.50	\$ 1,580.50		\$ 1,580.50
16	REAR LEFT TOWING METAL PLATE	1		\$480.50	\$ 480.50		\$ 480.50
17	REAR EXHAUST PIPE	1		\$2,311.60	\$ 2,311.60		\$ 2,311.60
18	REAR EXHAUST PIPE MOUNTING	1		\$49.10	\$ 49.10		\$ 49.10

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
19	REAR EXHAUST PIPE GASKET	1		\$50.30	\$ 50.30		\$ 50.30
20	TAIL GATE	1		\$2,460.20	\$ 2,460.20		\$ 2,460.20
21	TAIL GATE SHOCK ABSORBER LH & RH	2		\$362.40	\$ 724.80		\$ 724.80
22	TAIL GATE WINDSCREEN INNER SEAL	1		\$48.00	\$ 48.00		\$ 48.00
23	TAIL GATE LEXUS LOGO	1		\$71.70	\$ 71.70		\$ 71.70
24	TAIL GATE (L) LOGO	1		\$85.80	\$ 85.80		\$ 85.80
25	TAIL GATE RX270 LOGO	1		\$80.50	\$ 80.50		\$ 80.50
26	TAIL GATE REFLECTOR LH & RH	2		\$457.10	\$ 914.20		\$ 914.20
27	REAR NO PLATE WITH CASING	1		\$45.00	\$ 45.00		\$ 45.00
28	TAIL LAMP LH & RH	2		\$733.20	\$ 1,466.40		\$ 1,466.40
29	REAR FENDER LH & RH	2		\$1,545.10	\$ 3,090.20		\$ 3,090.20
30	WINDSCREEN SEALANT	1		\$40.00	\$ 40.00		\$ 40.00
SUBTOTAL					\$ 25,445.90	SUBTOTAL	\$ 25,445.90
GST 7%					\$ 1,781.21	GST 7%	1781.21
TOTAL					\$ 27,227.11	TOTAL	\$ 27,227.11

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

