

DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619

TEL: 6668 1122 | FAX: 6668 1123

18 SMRT Hui Eler.

## QUOTATION

DATE: 14/9/2021

REF: SDG8225G VEHICLE NO.: SDG8225G

MAKE: LEXUS MODEL: RX270

PREPARED BY: POON

## **QUOTATION FOR**

NAME: MS FIRST CAPITAL INSURANCE CLAIMS DEPARTMENT

COMPANY NAME: MS FIRST CAPITAL INSURANCE STREET ADDRESS: 36, Robinson Road, #16-01, City House

POSTAL CODE: 068877 PHONE: (65) 6507 3848

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR						
1	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELL IN PLACE NEW PANELS WITH FULL ALIGNMENT	1		\$1,500.00	\$ 1,500.00	60	1,500.0
2	TO PROVIDE SKILL LABOUR AND MATERIAL TO PREPARE AND PAINT ALL NEW PART AND PANELS	1		\$1,200.00	\$ 1,200.00		\$/ 3 1,200.0
3	TO USE CHASSIS ALIGNMENT EQUIPMENT. TO REALIGN BACK REAR LH CHASSIS	1		\$750.00	\$ 750.00		\$ 20 750.0
4	TO REMOVE AND REFIX AND REPLACE EXHAUST PIPE WITH FULL ALIGNMENT	1	1210	\$200.00	\$ 200.00		\$ 100 200.0
5	TO REMOVE AND REFIX REAR WINDSCREEN	1	1110	\$160.00	\$ 160.00		\$ 160.0
6	TO REMOVE AND REFIX ALL REAR WIRING AND REPLACE REVERSE SENSOR	1		\$200.00	\$ 200.00		\$ 60 2000
7	TO DO ELECTRICAL 4 WHEEL ALIGNMENT	1		\$200.00	\$ 200.00		\$ 200.0
	PARTS						
1	REAR BUMPER Distilled	1		\$960.30	\$ 960.30		\$ 960.3
2	REAR BUMPER CLIPS	10		\$5.50	\$ 55.00		\$ 30.55.
3	REAR BUMPER REFLECTOR LH & RH	SHOW		\$282.60	\$ 565.20		\$ 565.
4	REAR BUMPER SIDE RETAINER BIG	alle 2		\$125.40	\$ 250.80		\$ 250.8
5	REAR BUMPER SIDE RETAINER  SMALL LH & RH	tor m <sub>2</sub>		\$116.50	\$ 233.00		\$ 233.
6	REAR BUMPER REINFORCEMENT	Hem		\$738.10	\$ 738.10		\$ 738.
7	REAR BUMPER SPONGE	Cruhd1		\$173.10	\$ 173.10		\$ 173.
8	REVERSE SENSOR 4 PCS 2 PI	ces day		\$392.80	\$ 1,571.20		\$0.011.
9	REAR END PANEL Pers	1		\$918.50	\$ 918.50		\$ 3 918.
10	REAR SPARE TYRE HOUSING	5 1		\$991.70	\$ 991.70	000	\$ + 991.
11	REAR UNDER COVER LH SIDE	ichd 1		\$699.70	\$ 699.70	284	0.
12	REAR UNDER COVER LH SIDE CLIPS	le 10		\$10.80	\$ 108.00	.0	1
13	REAR UNDER COVER RH SIDE	10(N1		\$418.50	\$ 418.50	17	\$ 418
14	REAR UNDER COVER RH SIDE CLIPS	5 Mh		\$10.80	\$ 54.00	90	\$ 54
15	REAR LEFT CHASSIS Regis	1		\$1,580.50	\$ 1,580.50		\$ 1,580.
16	REAR LEFT TOWING METAL PLATE	Report 1		\$480.50	\$ 480.50	./ 2/	\$ 480
17	REAR EXHAUST PIPE Bent	1		\$2,311.60	\$ 2,311.60	1676	\$ 2,311
18	REAR EXHAUST PIPE MOUNTING	MY 1		\$49.10	\$ 49.10		\$ 49.

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT		DISC	AMOUNT
19	REAR EXHAUST PIPE GASKET	1		\$50.30	\$	50.30		\$ 50.30
20	TAIL GATE Res 5	1		\$2,460.20	\$	2,460.20		\$ 2,460.20
21		Hen 2		\$362.40	\$	724.80		\$ 724.80
22	TAIL GATE WINDSCREEN INNER SEAL	n 1		\$48.00	\$	48.00		\$ 48.00
23	TAIL GATE LEXUS LOGO	1		\$71.70	\$	71.70		\$ 71.70
24	TAIL GATE (L) LOGO	/ 1		\$85.80	\$	85.80		\$ 85.80
25	TAIL GATE RX270 LOGO	1		\$80.50	\$	80.50		\$ 80.50
26	TAIL GATE REFLECTOR LH & RH	2		\$457.10	\$	914.20		\$ + 914.20
27	REAR NO PLATE WITH CASING	1		\$45.00	\$	45.00		\$ 45.00
28	TAIL LAMP LH & RH	2		\$733.20	\$	1,466.40		\$ 1,466.40
29		2		\$1,545.10	\$	3,090.20		\$ + 3,090.20
30	REAR FENDER LH & RH WINDSCREEN SEALANT	1		\$40.00	\$	40.00		\$ + 40.00
				SUBTOTAL	\$	25,445.90	SUBTOTAL	\$ 25,445.90
REMARKS:		4416.	0	GST 7%	\$	1,781.21	GST 7%	1781.21
	100 101	:4028.	85	TOTAL	\$	27,227.11	TOTAL	\$ 27,227.11

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

FOR DICKSON AUTO CARE CENTRE PTE LTD

(AUTHORISED SIGNATURE)

tolel 573885 Adrian hing LS: 4.6K. 45 15/09/21

06 Pays.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poon 96902951