

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009639/BUCN2**Date:** 28/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00122282000

Claimant Vehicle No : SJC3111J **Insured Vehicle No :** GBE5789A

Date of Loss: 10/09/2021 Nature of Claim: TP Claim No: SNM21D205180/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC3111J**

Make & Model: AUDI RS3, 2.5 Sportback (A) Engine No: CEP006774

Reg. Date: 31/10/2011 (Man. Year: 2011) Chassis No: WUAZZZ8P1C1901110

Colour: Red Odometer: 138863 km

Engine Capacity: 2480 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35ZR19 Rear Tyre Size: 235/35ZR19

Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,629.20	24,441.32	19,187.88	43.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,350.00	2,490.00	64.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	47,469.20	25,791.32	21,677.88	45.67
Approved Total (Overridden) (\$\$)		20,650.00		
(\$\$)	47,469.20	20,650.00	26,819.20	56.50
+ GST 7.00/7.00% (\$\$)	3,322.84	1,445.50	1,877.34	56.50
Nett Amount (\$\$)	50,792.04	22,095.50	28,696.54	56.50

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 15/09/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Dec 2021)	
Parts:	N/A	AUDI RS3 2.5 Sportback (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC3111J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,405.00 FL	*2,405.00 FL
2	1		*BONNET RH HINGE	Not Damaged	58.00 FL	*- FL
3	1		*BONNET LH HINGE	Not Damaged	58.00 FL	*- FL
4	1		*BONNET LOCK	Not Damaged	214.00 FL	*- FL
5	1		*FRONT BUMPER	Broken	6,400.00 FL	*4,293.60 FL
6	1		*FRONT BUMPER RH GRILLE	Missing	421.00 FL	*337.00 FL
7	1		*FRONT BUMPER RH GRILLE TRIM	Missing	203.00 FL	*203.00 FL
8	1		*FRONT BUMPER RH BRACKET	Broken	315.00 FL	*315.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	1,253.00 FL	*1,065.90 FL
10	1		*FRONT BUMPER SPONGE	Broken	272.00 FL	*272.00 FL
11	1		*FRONT BUMPER TOWING COVER	Missing	97.00 FL	*97.00 FL
12	1		*FRONT RH HORN (HIGH TONE)	Not Damaged	226.00 FL	*- FL
13	1		*FRONT RH HORN BRACKET (HIGH TONE)	Not Damaged	66.00 FL	*- FL
14	1		*FRONT RH HORN (LOW TONE)	Not Damaged	226.00 FL	*- FL
15	1		*FRONT RH HORN BRACKET (LOW TONE)	Not Damaged	66.00 FL	*- FL
16	1		*RH HEADLAMP	Broken	2,906.00 FL	*2,906.00 FL
17	1		*RH HEADLAMP NOZZLE WASHER	Missing	204.00 FL	*204.00 FL
18	1		*RH HEADLAMP NOZZLE COVER	Missing	58.00 FL	*58.00 FL
19	1		*RH HEADLAMP LOWER BRACKET	Broken	118.00 FL	*118.00 FL
20	1		*FRONT GRILLE	Broken	4,249.00 FL	*2,226.00 FL
21	1		*FRONT GRILLE NUMBER PLATE HOLDER	Not Damaged	118.00 FL	*- FL
22	1		*SUPPORT PANEL	Broken	2,315.00 FL	*2,315.00 FL
23	1		*FRONT RH FENDER	Broken	6,372.00 FL	*6,372.00 FL
24	1		*FRONT RH FENDER SPLASH SHIELD	Torn	93.00 FL	*93.00 FL
25	1		*RH FRONT SPORT RIM	Not Damaged	1,379.00 FL	*- FL
26	1		*RH FRONT KNUCKLE ARM	Not Damaged	665.00 FL	*- FL
27	1		*RH FRONT SHOCK ABSORBER	Not Damaged	357.00 FL	*- FL
28	1		*RH FRONT UPPER ARM	Not Damaged	93.00 FL	*- FL
29	1		*RH FRONT LOWER ARM	Not Damaged	381.00 FL	*- FL
30	1		*STEERING RACK AND PINION	Not Damaged	5,182.00 FL	*- FL
31	1		*AIRCON CONDENSER	Not Damaged	1,092.00 FL	*- FL
32	1		*RADIATOR ASSY	Not Damaged	3,751.00 FL	*- FL
33	1		*TURBO INTERCOOLER	Broken	2,363.00 FL	*2,363.00 FL
34	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*SET BONNET INSULATOR CLIPS	Necessary	80.00 FS	*30.00 FS
36	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS
37	1		*FRONT RH TYRE	Not Necessary	450.00 FS	*- FS
38	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FS	*20.00 FS
39	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
40	1		*FRONT NUMBER PLATE	Not Damaged	80.00 FS	*- FS
41	1		*RH FRONT WHEEL BEARING	Not Damaged	960.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	45,876.00	25,723.50
- List Item Discount on L Items 5.00/5.00% (\$\$)	2,246.80	1,282.18
Total Parts (\$\$)	43,629.20	24,441.32

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	70.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR	New	220.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY,HOSES AND FAN ASSY TO ASSIST REPAIR	New	220.00	0.00
7	RESET AND DIAGNOSE ELECTRONIC CONTROL UNIT TO ASSIST REPAIR	New	380.00	120.00
8	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	550.00	0.00
9	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			3,840.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >