



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M033ZC

Date: 29th Sep 2021

Our Ref: CS3/ASM21003347/T1vce2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chong Arnold

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBP 280A

INSURED VEHICLE: SJX 694C

ACCIDENT DATE: 24/02/2021

We thank you for your instruction on 14/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBP 280A from M/s Pro-Option Services.
- b) Singapore Accident Statement of Vehicles FBP 280A and SJX 694C.
- c) Final Repair Bill of FBP 280A from M/s FTA Performance Pte Ltd.
- d) Colour damaged vehicle photographs of FBP 280A.

Pre-Repair Inspection Date : 16/03/2021 at M/s FTA Performance Pte Ltd, 8 Kaki Bukit Avenue 4, #07-26 Premier @ Kaki Bukit, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBP 280A
Make & Model	: Yamaha MT-09 ABS Tracer GT
Year of Registration	: 2019
Chassis Number	: JYARN575000009325
Engine Capacity	: 847 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.