

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21009647/TGA3Q2**Date:** 08/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900170399
Claimant Vehicle No :	SLG6389K	Insured Vehicle No :	SLT8279M
Date of Loss:	13/09/2021	Nature of Claim:	TP
		Claim No:	2127023183SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6389K	Engine No:	B14NET162010713
Make & Model:	CHEVROLET ORLANDO, 1.4 Turbo (A)	Chassis No:	KL1YA7589HK606102
Reg. Date:	07/10/2016 (Man. Year: 2016)	Odometer:	69167 km
Colour:	White		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,253.00	3,065.40	1,187.60	27.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,272.00	1,172.00	2,100.00	64.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,525.00	4,237.40	3,287.60	43.69
+ GST 7.00/7.00% (\$\$)	526.75	296.62	230.13	43.69
Nett Amount (\$\$)	8,051.75	4,534.02	3,517.73	43.69
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
Nett Liability (\$\$)		4,714.02		

INSPECTION

Date of Assignment:	17/09/2021		
Date Inspected:	17/09/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,283.00 FS	*1,154.70 FS
2	1		*REAR BUMPER PAD	Deformed	97.00 FS	*87.30 FS
3	1		*REAR BUMPER REFLECTOR-LH	Cut	63.00 FS	*56.70 FS
4	1		*REAR BUMPER FOG LAMP-CENTER	Not Necessary	215.00 FS	*- FS
5	1		*REAR BUMPER BRACKET-LH/RH	Ns Necessary/Os Not Necessary	54.00 FS	*24.30 FS
6	1		*REAR BUMPER BRACKET-CENTER	Not Necessary	74.00 FS	*- FS
7	1		*REAR BUMPER SIDE GUIDE-LH/RH	Ns Necessary/Os Not Necessary	64.00 FS	*28.80 FS
8	1		*REAR BUMPER LOWER	Deformed	630.00 FS	*567.00 FS
9	1		*REAR BUMPER LOWER SPOILER (SILVER)	Deformed	275.00 FS	*247.50 FS
10	1		*REAR BUMPER SENSOR BRACKET-RH	Not Necessary	12.00 FS	*- FS
11	1		*REAR BUMPER SENSOR BRACKET-CENTER	Not Necessary	24.00 FS	*- FS
12	1		*REAR BUMPER SENSOR BRACKET-LH	Not Necessary	12.00 FS	*- FS
13	1		*REAR BUMPER REINFORCEMENT	Bent	975.00 FS	*877.50 FS
14	2		*REAR WHEEL ARCH TRIM-LH/RH	Not Necessary	275.00 FS	*- FS
15	1		*SUNDRIES	Necessary	200.00 FS	*21.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,253.00	3,065.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR REAR LID AND REAR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	350.00
3	TO RESPRAY REAR BUMPER,REAR LID AND REAR END PANELLING	New	1,600.00	350.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,272.00	1,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >