

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 6389 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,283.00	de ✓
2	REAR BUMPER PAD	1	\$ 97.00	de ✓
3	REAR BUMPER REFLECTOR - LH	1	\$ 63.00	ad ✓
4	REAR BUMPER FOG LAMP - CENTER	1	\$ 215.00	X NN
5	REAR BUMPER BRACKET - LH / RH	2	\$ 54.00	LH nec RHx NN 27
6	REAR BUMPER BRACKET - CENTER	1	\$ 74.00	? XNN
7	REAR BUMPER SIDE GUIDE - LH / RH	2	\$ 64.00	LH nec - RHx NN 32
8	REAR BUMPER LOWER	1	\$ 630.00	de ✓
9	REAR BUMPER LOWER SPOILER (SILVER)	1	\$ 275.00	de ✓
10	REAR BUMPER SENSOR BRACKET - RH	1	\$ 12.00	X NN
11	REAR BUMPER SENSOR BRACKET - CENTER	1	\$ 24.00	X NN
12	REAR BUMPER SENSOR BRACKET - LH	1	\$ 12.00	? XNN
13	REAR BUMPER REINFORCEMENT	1	\$ 975.00	? BT ✓
14	REAR WHEEL ARCH TRIM - LH / RH	2	\$ 275.00	? XNN
15	SUNDRIES	\$	200.00	? 24 NEC ✓
TOTAL SPARE PARTS		:	\$ 4,253.00	3406
TOTAL LABOUR CHARGES		:	\$ 3,272.00	10%- 3065.40
GRAND TOTAL		:	\$ 7,525.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

1172
 3065.40
 \$4237.40
 3 days #

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
WP' 17/9/21 @ 1015
3 days
Resurvey before permit
Tanpin e 11/11/2021

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 6389 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	1,200.00	350.
3	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	1,600.00	350
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	3,272.00	1172