

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0750/2021/JT
DATE : 15-Sep-21
WIP : 44452

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 17/9/21

YOUR INSURED VEH NO : SLT 8279 M

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Hi Taufik,

3 days - ok - Jy - 16 Nov 21

OWNER'S NAME : MS TANG SHIH MAI
ADDRESS : BLK 734 UPPER CHANGI ROAD EAST
#01-23
SINGAPORE 486862
TELEPHONE : HP +65 98187721
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5084842718-04
VEHICLE NO : SLG 6389 K
MODEL CODE : CHEVROLET ORLANDO 1.4
MODEL YEAR : 07/10/2016
ENGINE NO : B14NET162010713
CHASSIS NO : KL1YA7589HK606102
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-21
PLACE OF ACCIDENT : IN FRONT OF UPPER CHANGI MRT/
SUTD ALONG UPPER CHANGI ROAD EAST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 6389 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$	350.00
3	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	1,600.00	\$	350.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 3,272.00	\$	1,172.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 6389 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,283.00	\$ 1,283.00
2	REAR BUMPER PAD	1	\$ 97.00	\$ 97.00
3	REAR BUMPER REFLECTOR - LH	1	\$ 63.00	\$ 63.00
4	REAR BUMPER FOG LAMP - CENTER	1	\$ 215.00	
5	REAR BUMPER BRACKET - LH / RH	2	\$ 54.00	\$ 27.00
6	REAR BUMPER BRACKET - CENTER	1	\$ 74.00	
7	REAR BUMPER SIDE GUIDE - LH / RH	2	\$ 64.00	\$ 32.00
8	REAR BUMPER LOWER	1	\$ 630.00	\$ 630.00
9	REAR BUMPER LOWER SPOILER (SILVER)	1	\$ 275.00	\$ 275.00
10	REAR BUMPER SENSOR BRACKET - RH	1	\$ 12.00	
11	REAR BUMPER SENSOR BRACKET - CENTER	1	\$ 24.00	
12	REAR BUMPER SENSOR BRACKET - LH	1	\$ 12.00	
13	REAR BUMPER REINFORCEMENT	1	\$ 975.00	\$ 975.00
14	REAR WHEEL ARCH TRIM - LH / RH	2	\$ 275.00	
15	SUNDRIES		\$ 200.00	\$ 24.00
TOTAL SPARE PARTS		:	\$ 4,253.00	\$ 3,406.00
TOTAL LABOUR CHARGES		:	\$ 3,272.00	\$ 1,172.00
GRAND TOTAL		:	\$ 7,525.00	\$ 4,578.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-08/10/21

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT