



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2304650

INV Date 19/07/2023

Reference CC4/LPC21009649/Kya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GX 836X
Insured Veh. YN 5226M
Claim No. 21/21/21/VC00/024949
Policy No. Z/21/VC00/111157
Accident Date 09/09/2021
Inspection Date 27/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Ref: CC4/LPC21009649/Kya3q2

Date: 19/07/2023

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5226M	Veh. Inspected	GX 836X
Policy No.	Z/21/VC00/111157	Coverage (\$)	0.00
Claim No.	21/21/21/VC00/024949	Excess (\$)	0.00
Assign From	GERALD	Assign Date	15/09/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ VITO 109 CDI	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WDF44760323492214	Colour	WHITE
Odometer	30001 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MICHELIN	8 mm
L/H Front Tyre	205/65 R16	MICHELIN	8 mm
R/H Rear Tyre	205/65 R16	MICHELIN	8 mm
L/H Rear Tyre	205/65 R16	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/09/2021	Inspection Date	27/09/2021
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 836X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH SIDE MIRROR	CRACKED	1,250.00	1,250.00
1	FRONT RH SIDE MIRROR COVER	DENTED	96.00	96.00
1	FRONT RH SIDE MIRROR GLASS	SERVICEABLE	101.00	-
	LESS 10% DISCOUNT		-144.70	-134.60
			1,302.30	1,211.40
	<u>LABOUR</u>			
	REMOVE & REFIX FRT RH SIDE MIRROR & RESET SYSTEM.		100.00	60.00
			100.00	60.00
	GRAND TOTAL		1,402.30	1,271.40
RECOMMENDED COST OF REPAIRS				1,271.40

Report Ref No. CC4/LPC21009649/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GX 836X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GX 836X

RE-INSPECTION

