

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 01 Oct 2021

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SMR897E | Accident Date | : 12/09/2021 |
| TP Vehicle No | : SLG7239D | Assignment Date | : 15/09/2021 |
| Make | : HONDA CIVIC | Est. Duration of Repair | : 8 |
| Date of Inspection | : 17/09/2021 | | |
| Inspection At | : BIFROST AUTO PTE LTD (KAKI BUKIT) 8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT SINGAPORE 415875 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 23,299.04 |
| Revised Amount | :S\$ | 10,756.02 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 10,756.02 |
| Lump Sum Repair | :S\$ | 6,400.00 |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 13,000.00 |
| COE / PARF Rebate | :S\$ | 6,507.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 6,493.00 |

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .