

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0753/2021/ZK

20-Sep-21

CHANG

1 of 1

SKW 1173 B

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	RADIATOR AIR GUIDE - LH INNER / TN	\$ 16.00	13.52
2	AIR INTAKE AIR GUIDE / BR	\$ 53.00	42.4
3	HORN CONNECTOR / BR	\$ 21.00	16.4
4	BONNET LOCK CONNECTOR / BR	\$ 13.00	10.32
5	INTAKE CONNECTOR / BR	\$ 31.00	24.08
6	WIRING SEAL / NPC	\$ 15.00	11.61
7	WIRING REPAIR KIT / NPC	\$ 130.00	103.36
GRAND TOTAL		\$ 279.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Steve
21/9/21

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 1173 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO REMOVE AN REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR , RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT PRESSURISE COOLING SYSTEM TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,700.00 / (photo)	
4	TO REMOVE AND REINSTALL RHS FRONT SUSPENSION ASSY WITH SUBFRAME TO INSPECT FOR DAMAGES AND RENEW IF NECESSARY	S/N \$ 2,400.00 /	
5	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS	S/N \$ 560.00 280	
6	TO REMOVE AND RENEW RHS ENGINE MOUNTING ASSY	S/N \$ 280.00 ?	
SUB LABOUR CHARGES		: \$ 5,820.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 1173 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. TO REPAIR RHS FRONT DOORS AND RHS FRONT UPPER A-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	2750 + 1500 (lock carrier) + 250 (repair front door)
8	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS FRONT FENDER TOP SUPPORT, BOTH FRONT UPPER A-PILLAR AND BOTH FRONT DOORS	\$ 7,600.00	3925
9	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	S/N \$ 800.00	?
10	TO PUT ON THE CAR ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	?
11	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	/
12	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 25,524.00	

Car in

17/9/21 wip=44054

cam/choy.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

11G- Steve.

12 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1173 B

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER ✓ BR ?	1	\$ 2,342.00	
2	FRONT BUMPER SECURING STRIP ✓ CUT MIS	2	\$ 71.00	
3	FRONT BUMPER GRILLE ✓ BR	1	\$ 196.00	
4	FRONT BUMPER CLOSING ELEMENT ✓ BR	1	\$ 262.00	
5	FRONT BUMPER SPOILER ? ✓ CUT	1	\$ 535.00	
6	FRONT BUMPER AIR GUIDE - RH ? ✓ BR	1	\$ 63.00	
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 262.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH ✓ BR	1	\$ 135.00	
9	FRONT BUMPER TRIM - RH ? ✓ CUT	1	\$ 48.00	
10	FRONT BUMPER TRIM - CENTER ?	1	\$ 114.00	
11	RADIATOR GRILLE ✓ BR	1	\$ 1,694.00	
12	FRONT BUMPER REINFORCEMENT FOAM PIECE ? ✓ BR	1	\$ 146.00	
13	FRONT BUMPER REINFORCEMENT BAR ? ✓ BT	1	\$ 845.00	
14	FRONT BUMPER GUIDE SECTION - RH ✓ BR	1	\$ 36.00	
15	FRONT BUMPER BRACKET - RH ?	1	\$ 214.00	
16	FRONT BUMPER TOP COVER ✓ CRW	1	\$ 127.00	
17	CAUTION STICKER ✓ MK	1	\$ 14.00	
18	AIR CONDITIONER STICKER ✓ MK	1	\$ 8.00	
19	FRONT BUMPER REINFORCEMENT BRACKET ? ✓ BR	1	\$ 137.00	
20	FRONT BUMPER SUPPORT - LH/RH ? ✓ MK	1	\$ 58.00	
SUB TOTAL SPARE PARTS			\$ 7,307.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1173 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	POP RIVET <i>NR</i>	4	\$	4.00
22	HORN - RH <i>OR</i>	1	\$	126.00
23	HORN BRACKET - RH <i>BT</i>	1	\$	29.00
24	FRONT PARKING AID SENSOR - RH OUTER <i>- mis</i>	1		TBC
25	FRONT PARKING AID SENSOR - RH INNER <i>- mis</i>	1		TBC
26	FRONT PARKING AID SENSOR SEAL <i>NR</i>	4	\$	14.00
27	FRONT BUMPER WIRING <i>TNI</i>	1	\$	405.00
28	FRONT BONNET <i>BT</i>	1	\$	3,312.00
29	FRONT BONNET RETAINING CLIP <i>NR</i>	3	\$	4.00
30	FRONT BONNET ATTACHMENT PARTS <i>X</i>	1	\$	123.00
31	FRONT BONNET HINGE - LH / RH <i>1</i>	2	\$	838.00
32	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER <i>NR</i>	1	\$	84.00
33	FRONT BONNET INSULATION <i>CR4</i>	1	\$	343.00
34	FRONT BONNET STRIKER <i>1</i>	1	\$	50.00
35	FRONT BONNET LOCK <i>1</i>	1	\$	214.00
36	FRONT BONNET BOWDEN CABLE - CENTER <i>1</i>	1	\$	58.00
37	FRONT BONNET HOOD RELEASE <i>1</i>	1	\$	14.00
38	FRONT BONNET RELEASE CABLE <i>1</i>	1	\$	58.00
39	FRONT BONNET CABLE COVER <i>1</i>	1	\$	10.00
40	FRONT BONNET LOCK CABLE - RH <i>1</i>	1	\$	74.00
SUB TOTAL SPARE PARTS		:	\$	5,760.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NOBA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1173 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	PLENUM CHAMBER COVER - RH ?	1	\$ 97.00	
42	FRONT FENDER TOP COVER - RH / Nec	1	\$ 72.00	
43	FRONT BONNET STRUT X	1	\$ 121.00	
44	FRONT FENDER - RH / OO	1	\$ 1,060.00	
45	FRONT FENDER ATTACHEMENT PART / Nec	1	\$ 53.00	
46	FRONT FENDER SUPPORT BRACKET / Nec	1	\$ 74.00	
47	FRONT FENDER BRACKET - RH / Nec	1	\$ 35.00	
48	POP RIVET / Nec	5	\$ 17.00	
49	FRONT FENDER RETAINING BRACKET - RH / Nec	1	\$ 49.00	
50	FRONT FENDER SUPPORT / Nec	1	\$ 35.00	
51	FRONT FENDER BRACKET - REAR RH / Nec	1	\$ 58.00	
52	FRONT FENDER HOLE COVER / Nec	1	\$ 18.00	
53	FRONT FENDER BRACE - RH ? / OO	1	\$ 118.00	
54	FRONT FENDER CLOSING ELEMENT - RH / Nec	1	\$ 33.00	
55	FRONT HEADLIGHT COVER - RH / BR	1	\$ 44.00	
56	FRONT FENDER COVER - RH / MIS	1	\$ 16.00	
57	FRONT FENDER COVER - OUTER RH / Nec	1	\$ 36.00	
58	FRONT FENDER TRIM - RH / CAT	1	\$ 164.00	
59	FRONT WHEEL HOUSING LINER - RH / CR4	1	\$ 275.00	
60	FRONT WHEEL HOSUING LINER ATTACHMENT PART X	1	\$ 169.00	
SUB TOTAL SPARE PARTS		:	\$ 2,544.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1173 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	FRONT WHEEL SPOILER - RH ✓ MIS	1	\$	73.00	
62	FRONT SPOILER - RH ✓ MIS	1	\$	36.00	
63	FRONT FENDER STONE CHIP GUARD - RH ? / npe	1	\$	51.00	
64	FRONT FENDER BRACKET TRIM - RH ?	1	\$	24.00	
65	FRONT FENDER CONNECTING PLATE - RH ? / DD	1	\$	217.00	
66	FRONT FENDER FILLER PANEL - RH ✓ / DD	1	\$	251.00	
67	FRONT HEADLIGHT - RH ✓ BR	1	\$	7,685.00	
68	FRONT HEADLIGHT COMPENSATING PIECE ✓ / BT	2	\$	83.00	
69	FRONT HEADLIGHT RETAINER PLATE ?	2	\$	80.00	
70	FRONT HEADLIGHT SPACER ?	2	\$	80.00	
71	FRONT HEADLIGHT HOSE - RH ?	1	\$	36.00	
72	FRONT HEADLIGHT LIFT CYLINDER - RH ? / BR	1	\$	198.00	
73	FRONT HEADLIGHT LIFT CYLINDER BRACKET - RH ? / BR	1	\$	15.00	
74	FRONT HEADLIGHT LIFT CYLINDER HOSE ? / 714	1		TBC	
75	FRONT HEADLIGHT LIFT CYLINDER CONNECTED HOSE ?	1	\$	46.00	
76	FRONT WASHER RESERVOIR ?	1	\$	142.00	
77	WINDSCREEN WASHER PUMP ?	1	\$	125.00	
78	HEADLIGHT WASHER PUMP ?	1	\$	155.00	
79	RADIATOR LOCK CARRIER ? / BT	1	\$	1,016.00	
80	RADIATOR SUPPORT ?	1	\$	38.00	
SUB TOTAL SPARE PARTS			:	\$	10,351.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1173 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	AIR COOLER	1	\$	587.00
82	AIR COOLER SEAL	1	\$	92.00
83	AIR COLLER PRESSURE HOSE - RH	1	\$	357.00
84	FRONT BUMPER TEMPERATURE SENSOR BRACKET	1	\$	19.00
85	COOLANT	6	\$	266.00
86	RADIATOR AIR GUIDE - RH OUTER	1	\$	32.00
87	RADIATOR AIR GUIDE - RH INNER	1	\$	16.00
88	RADIATOR AIR DUCT - RH UPPER	1	\$	16.00
89	RADIATOR AIR DUCT - RH LOWER	1	\$	22.00
90	AIR FILTER	1	\$	386.00
91	WINDSCREEN STRIP - LH / RH	2	\$	134.00
92	FRONT DOOR CHORMETRIM - LH / RH	2	\$	328.00
93	FRONT WINDOW CHROME SLOT SEAL - LH / RH	2	\$	798.00
94	FRONT ALUMINIUM RIM - RH	1	\$	2,290.00
95	FRONT SUBFRAME	1	\$	2,290.00
96	FRONT SUBFRAME SUPPORT - RH	1	\$	472.00
97	ENGINE MOUTING - RH	1	\$	370.00
98	ENGINE MOUTING SUPPORT - RH	1	\$	158.00
99	ENGINE BEARING SUPPORT - RH	1	\$	67.00
100	FRONT LOWER ARM WISHBONE - RH	1	\$	539.00
SUB TOTAL SPARE PARTS			\$	9,239.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5KW 1173 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
101	FRONT LOWER ARM - RH ARM <i>2</i> <i>BT</i>	1	\$	943.00	
102	FRONT UPPER ARM - RH FRONT <i>1</i> <i>BT</i>	1	\$	512.00	
103	FRONT UPPER ARM - RH REAR <i>1</i> <i>BT</i>	1	\$	512.00	
104	WHEEL BEARING HOUSING - RH <i>1</i> <i>BT</i>	1	\$	968.00	
105	FRONT LOWER BALL JOINT <i>1</i> <i>MC</i>	1	\$	193.00	
106	FRONT WHEEL HUB <i>1</i> <i>MC</i>	1	\$	479.00	
107	FRONT WHEEL BEARING <i>1</i> <i>MC</i>	1	\$	246.00	
108	FRONT SUSPENSION FORKS - RH <i>1</i> <i>BT</i>	1	\$	264.00	
109	STABILIZER LINK - RH <i>1</i>	1	\$	127.00	
110	FRONT ANTI ROLL BAR <i>1</i>	1	\$	433.00	
111	FRONT SHOCK ABSORBER - RH <i>1</i> <i>BT</i>	1	\$	310.00	
112	FRONT DRIVE SHAFT - RH <i>1</i>	1	\$	2,650.00	
113	STEERING RACK <i>1</i>	1	\$	6,787.00	
114	TIE ROD - RH <i>1</i>	1	\$	99.00	
115	TIE ROD END - RH <i>1</i> <i>BT</i>	1	\$	167.00	
116	UNDERBODY NOISE INSULATION <i>1</i> <i>MR</i>	1	\$	572.00	
117	UNDERBODY NOISE INSULATION FIXING PARTS <i>1</i> <i>X</i>	1	\$	70.00	
118	FRONT NO PLATE <i>1</i> <i>MC</i>	S/N	\$	60.00	
119	ACRYLIC SEALANT <i>1</i>	1	\$	180.00	
120	CAVITY WAX <i>1</i>	1	\$	140.00	
SUB TOTAL SPARE PARTS		:	\$	15,712.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1173 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
121	STONE CHIP	1	\$	180.00	
122	METAL FILLER POWDER	1	\$	280.00	
123	RHS FRONT TYRE	1		TBC	
124	SUNDRIES	1	\$	500.00	
TOTAL SPARE PARTS		:	\$	51,873.00	
TOTAL LABOUR CHARGES		:	\$	25,524.00	
GRAND TOTAL		:	\$	77,397.00	


ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0753/2021/ZK

5-Oct-21

CHANG

1 of 1

SKW 1173 B

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LAMBDA PROBE SENSOR - BT	\$ 507.00	405.2
GRAND TOTAL		\$ 507.00	

For Premium Automobiles Pte Ltd

Steve (LKK)
6/10/21




Authorised Signature

**Supplementary Estimate - 3**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0753/2021/ZK 10-Nov-21 CHANG 1 of 1 SKW 1173 B AUDI A5 SPORTBACK 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO CARRY OUT WIRING CHECK AND REPLACE S/N ACCORDING TO DAMAGE. CHECK FUNCTION.	\$ 280.00	280
GRAND TOTAL		\$ 280.00	

For Premium Automobiles Pte Ltd



Authorised Signature