

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 15 Sep 2021

Preliminary Advice

Vehicle No	: SKW1173B	Accident Date	: 12/09/2021
Make	: AUDI A5	Policy No.	: 7210000999
Assignment Date	: 15/09/2021	Excess	: S\$0.00
Date of Inspection	: 14/09/2021	Est. Duration of Repair	: 12
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 77,397.00
Revised Amount	:S\$ 38,967.00
Check Items (Estimated)	:S\$ 26,596.00
Total	:S\$ 65,563.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 170,000.00
COE / PARF Rebate	:S\$ 90,197.00
Salvage Value	:S\$

Margin for Repair

:S\$ 79,803.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.