



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0735/2021/ZK
DATE : 8-Sep-21
WIP : 43241

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM TEONG GUAN
ADDRESS : BLK 607 JURONG WEST STREET 65
#10-572
SINGAPORE 640607
TELEPHONE : HP +65 91074517
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800111711-02
VEHICLE NO : **SME 1364 M**
MODEL CODE : Q3 1.4 TFSI S
MODEL YEAR : 19/9/2018
ENGINE NO : CZD 876713
CHASSIS NO : WAUZZZ8U1JR100966
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Sep-21
PLACE OF ACCIDENT : BLK 607 JURONG WEST STREET 65 MSCP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 1364 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID, CHECK FUNCTION	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW REAR BUMPER SPOTLER. TO RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER, DOOR ENTRANCE AND LHS ILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00	550
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, DOOR ENTRANCE AND LHS FRONT DOOR.	\$ 5,000.00	1100
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	S/N \$ 280.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,752.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 1364 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Dented</i>	1	\$ 2,909.00	✓ 2327.2
2	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 172.00	✓ 137.2
3	REAR DOOR SEAL BRACKET - LH <i>new</i>	1	\$ 18.00	+
4	GROMMET <i>new</i>	3	\$ 8.00	+
5	REAR DOOR ATTACHMENT PART <i>new</i>	1	\$ 218.00	+
6	REAR DOOR CATCH - LH ?	1	\$ NN 120.00	? 410.4
7	FRONT AND REAR DOOR SOUL COVER - LH <i>new</i>	2	\$ 410.4 514.00	✓ 206.4
8	REAR WHEEL ARCH COVER - LH / RH <i>LH cut</i>	2	\$ 206.4 516.00	258
9	REAR SILL PANEL SEAL - LH <i>new</i>	1	\$ 65.00	+
10	REAR SPOILER <i>new</i>	1	\$ 475.00	+
11	REAR ALUMINIUM RIM - LH <i>new</i>	1	\$ 1,262.00	+
12	SUNDRIES ?		\$ NEC 300.00	? 1.92
TOTAL SPARE PARTS		:	\$ 6,577.00	
TOTAL LABOUR CHARGES		:	\$ 9,752.00	
GRAND TOTAL		:	\$ 16,329.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *12/09/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT