

卓亚水喷漆公司

TOH AH SWEE SPRAY PAINTING CO.

NO 60 JALAN LAM HUAT #07-33/34 CARROS CENTRE SINGAPORE 737869
 TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943
 EMAIL: claims@tohahswee.com.sg
 BUSINESS REG. NO: 09935300L
 GST REG. NO: 09-935300-L

14/9/2021

ERGO INSURANCE PTE. LTD.
 5 TEMASEK BOULEVARD
 #04-01 SUNTEC TOWER FIVE
 SINGAPORE 038985
 ATTN: MOTOR CLAIMS DEPT.

ESTIMATED REPAIR BILL

YOUR REF : YP2111U
 TYPE OF CLAIM : THIRD PARTY CLAIMS
 CLAIMANT : LOH VEE LIAN
 VEHICLE NO. : SKX3776T
 MAKE/ MODEL : HONDA ODYSSEY
 ACCIDENT DATE : 10/09/2021

MATERIAL COST

1PC	BUMPER <i>de/</i>	\$	1,090.00 <i>856</i>
1PC	REFLECTOR L AND R <i>X sue LH-? X sue</i>	\$	80.00 <i>X</i>
1PC	BOOTLID <i>bt/</i>	\$	1,800.00 <i>1172</i>
1PC	BOOTLID TAIL LAMP LHS <i>cm/</i>	\$	715.00 <i>400</i>
1PC	BOOTLID TAIL LAMP RHS <i>cm/</i>	\$	715.00 <i>400</i>
1PC	BOOTLID LOWER CHROME <i>cm/</i>	\$	450.00 <i>223</i>
1PC	BOOTLID UPPER CHROME <i>cm/</i>	\$	430.00 <i>284</i>
1PC	BOOTLID HYDRAULIC STAND RHS <i>X sue</i>	\$	300.00 <i>X</i>
1PC	BOOTLID HYDRAULIC STAND LHS <i>X sue</i>	\$	300.00 <i>X</i>
1PC	BOOTLID CENTRE LOCK <i>X sue</i>	\$	315.00 <i>X</i>
1PC	BOOTLID OPEN BUTTON <i>X sue</i>	\$	230.00 <i>X</i>
1PC	WIPER <i>sue/</i>	\$	95.00 <i>50</i>
1PC	WIPER MOTOR <i>? nu/</i>	\$	580.00 <i>298</i>
1PC	REVERSE SENSOR <i>? nu/ s/n</i>	\$	600.00 <i>200 s/n</i>
1PC	RECORD CAMERA <i>mi/ s/n</i>	\$	600.00 <i>400 s/n</i>
1PC	REVERSE CAMERA <i>cut/ s/n</i>	\$	700.00 <i>350 s/n</i>
1PC	REAR WINDSCREEN WITH MOULDING <i>re/</i>	\$	2,100.00 <i>1260</i>
1PC	SOLAR FLIM <i>n/ s/n</i>	\$	300.00 <i>s/n</i>
		\$	11,400.00
	LESS DISCOUNT 20%	\$	2,280.00
		\$	9,120.00

S/N-1250

4943
20%
3954.40

MATERIAL COST - SPECIAL NETT

1 PC REAR NUMBER PLATE *cm/* \$ 30.00 */*

LABOUR CHARGE :

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY. TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS.

PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

TO REMOVE AND REFIX REAR WINDSCREEN

TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING & INSTALLATION RECORD CAMERA

ADD : GST 7%

TOTAL :

\$	500	1,200.00
\$	400	1,200.00
\$	120	300.00
\$	200	600.00
\$		12,450.00
\$		871.50
\$		13,321.50

SINGAPORE DOLLARS

THIRTEEN THOUSAND THREE HUNDRED TWENTY ONE AND CENTS
FIFTY ONLY

NOTE: THE ESTIMATED PERIOD OF REPAIRS IS SIX (6) DAYS

TOH AH SWEE SPRAY PAINTING CO.
JUDY YIM (TEL:63660761)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
4 days
4S
15/09/21 @ 1330
Resy after repair

卓亚水喷漆公司 TOH AH SWEE SPRAY PAINTING CO.

NO 60 JALAN LAM HUAT #07-33/34 CARROS CENTRE SINGAPORE 737869

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

GST REG. NO: 09-935300-L

16/9/2021

ERGO INSURANCE PTE. LTD.

5 TEMASEK BOULEVARD

#04-01 SUNTEC TOWER FIVE

SINGAPORE 038985

ATTN: MOTOR CLAIMS DEPT.

ESTIMATED REPAIR BILL

YOUR REF	: YP2111U
TYPE OF CLAIM	: THIRD PARTY CLAIMS
CLAIMANT	: LOH VEE LIAN
VEHICLE NO.	: SKX3776T
MAKE/ MODEL	: HONDA ODYSSEY
ACCIDENT DATE	: 10/09/2021

H/S \$51300
4 days

3954.40
1250.00
1250.00
120.00
100.00
6674.40
20%
5339.52

MATERIAL COST-SUPPLEMENTARY PARTS

1PC	BUZZER ASSY	<i>ca</i>
1PC	WIPER MOTOR	
1PC	REVERSE CAMERA	<i>} inside</i>
1PC	REVERSE SENSOR	<i>} estimate</i>

150
20%
120

\$	150.00 ✓
\$	580.00
\$	700.00
\$	600.00
\$	2,030.00
\$	406.00
\$	1,624.00

LESS DISCOUNT 20%

LABOUR CHARGE :

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY. TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS.

\$	100.00 ✓
\$	1,724.00
\$	120.68
\$	1,844.68

ADD : GST 7%
TOTAL :

SINGAPORE DOLLARS

ONE THOUSAND EIGHT HUNDRED FOURTY FOUR AND CENTS
SIXTY EIGHT ONLY

TOH AH SWEE SPRAY PAINTING CO.
JUDY YIM (TEL:63660761)