

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Sep 2021

Preliminary Advice

Insured	: YP2111U		
Vehicle No			
TP Vehicle No	: SKX3776T	Accident Date	: 10/09/2021
Make	: HONDA ODYSSEY	Assignment Date	: 15/09/2021
Date of Inspection	: 15/09/2021	Est. Duration of Repair	: 4
Inspection At	: TOH AH SWEE SPRAY PAINTING CO (HQ) NO 60, JALAN LAM HUAT, #07-33/34 CARROS CENTRE SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,450.00
Revised Amount	:S\$	7,886.00
Check Items (Estimated)	:S\$	1,008.00
Total	:S\$	8,894.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.