

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009659/AGA3Q2**Date:** 13/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900107113-02
Claimant Vehicle No :	SLN6579S	Insured Vehicle No :	SKJ7731U
Date of Loss:	14/09/2021	Nature of Claim:	TP
		Claim No:	2839836167SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN6579S	Engine No:	3ZRB969925
Make & Model:	TOYOTA HARRIER, 2.0 PREMIUM CVT (A)	Chassis No:	ZSU600099667
Reg. Date:	12/05/2017 (Man. Year: 2017)	Odometer:	60967 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,881.35	1,982.85	5,898.50	74.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	510.00	2,570.00	83.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,961.35	2,492.85	8,468.50	77.26
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	10,961.35	2,000.00	8,961.35	81.75
+ GST 7.00/7.00% (S\$)	767.29	140.00	627.29	81.75
Nett Amount (S\$)	11,728.64	2,140.00	9,588.64	81.75
+ Car Rental (3.0 x S\$130.00/day) (S\$)		390.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,532.00		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment:	15/09/2021	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Date Inspected:	15/09/2021 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,317.80 FL	*1,317.80 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	230.10 FL	*- FL
3	1		*REAR BUMPER LOWER LIP	Cut	689.10 FL	*486.00 FL
4	1		*REAR FENDER LH	Not Necessary	1,341.10 FL	*- FL
5	1		*REAR FENDER INNER SHIELD LH	Not Necessary	210.10 FL	*- FL
6	1		*REAR SHOCK ABSORBER LH	Not Necessary	731.20 FL	*- FL
7	1		*REAR UPPER ARM LH	Not Necessary	789.10 FL	*- FL
8	1		*REAR ADJUSTER ARM LH	Not Necessary	711.20 FL	*- FL
9	1		*REAR LOWER ARM LH	Not Necessary	570.90 FL	*- FL
10	1		*REAR KNUCKLE ARM LH	Not Necessary	631.10 FL	*- FL
11	1		*REAR KNUCKLE ARM BEARING LH	Not Necessary	580.10 FL	*- FL
12	1		*RH REAR SPORT RIM	Cut	1,500.00 FS	*600.00 FS
13	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	1		*REAR TYRE LH	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,831.80	2,433.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,950.45	450.95
Total Parts (S\$)	7,881.35	1,982.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,000.00	200.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	200.00
3	LABOUR FOR REMOVE & RENEW LH REAR UNDERCARRIAGE	New	300.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
5	WIRING CHECK	New	80.00	30.00
6	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	0.00
7	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY/ROOF LINING CARPET	New	250.00	0.00
Gross Labour Cost (\$)			3,080.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >