

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009660/KEA3Q2**Date:** 28/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070036633
<b>Claimant Vehicle No :</b>	SJA7888K	<b>Insured Vehicle No :</b>	SLA1100R
Date of Loss:	14/09/2021	Nature of Claim:	TP
		Claim No:	7990072661SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJA7888K</b>	Engine No:	4GR0480360
Make & Model:	TOYOTA CROWN, 2.5 (A)	Chassis No:	GRS2000008981
Reg. Date:	06/08/2008 (Man. Year: 2008)	Odometer:	168446 km
Colour:	Metallic Dark Brown		
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35Z R19	Rear Tyre Size:	275/30Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,984.90	1,953.75	2,031.15	50.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,225.00	450.00	775.00	63.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,209.90</b>	<b>2,403.75</b>	<b>2,806.15</b>	<b>53.86</b>
<b>+ GST 7.00/7.00% (S\$)</b>	364.69	168.26	196.43	53.86
<b>Nett Amount (S\$)</b>	<b>5,574.59</b>	<b>2,572.01</b>	<b>3,002.58</b>	<b>53.86</b>
<b>+ Car Rental (2.0 x S\$150.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,874.01</b>		

INSPECTION

Date of Assignment:	15/09/2021	
Date Inspected:	08/10/2021	Inspected At: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	2,570.00 FL	*2,570.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	369.70 FL	*- FL
4	1		*REAR END PANEL	Repair	620.70 FL	*- FL
5	1		*REAR BOOT INNER LOCK	Repair	1,057.00 FL	*- FL
6	1		*REAR BOOT BADGE CROWN	Not Necessary	46.20 FL	*- FL
7	1		*REAR BOOT BADGE ATHLETE	Not Necessary	62.20 FL	*- FL
8	1		*REAR BOOT EMBLEM	Not Necessary	50.70 FL	*- FL
9	1		*REAR BOOT CHROME MOULDING	Serviceable	501.70 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,313.20</b>	<b>2,605.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,328.30	651.25
<b>Total Parts (\$)</b>	<b>3,984.90</b>	<b>1,953.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND TO REWELD ,RESHAPE AND REPAIR REAR END PANEL ,REAR FLOOR PANEL ,REAR BODY PANEL ,TO STRAIGHTEN OUT REAR CHASSIS MEMBER ,TO REPLACE DAMAGED PARTS AND ADJUST REAR BODY AND BOOT ALIGNMENT	New	550.00	200.00
2	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	650.00	250.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	25.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>1,225.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >