#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21009661/KTF3E2

**Date:** 04/10/2021

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SLN7543M Insured Vehicle No : GBE3253S

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: CDMCG21001785-001

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLN7543M

 Make & Model:
 HONDA VEZEL, 1.5 HYBRID X (A)
 Engine No:
 LEB5938251

 Reg. Date:
 17/05/2017 (Man. Year: 2017)
 Chassis No:
 RU31238236

 Colour:
 Metallic Red
 Odometer:
 52164 km

Engine Capacity: 1496 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,950.08	2,616.64	1,333.44	33.76
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,540.00	1,140.00	400.00	25.97
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,490.08	3,756.64	1,733.44	31.57
	Approved Total (Overridden) (S\$)		3,000.00		
	Nett Amount (S\$)	5,490.08	3,000.00	2,490.08	45.36

**INSPECTION** 

Date of Assignment: 15/09/2021

King's Auto Spray Paint Pte Ltd (HQ)

Date Inspected: 20/09/2021 Inspected At: BLK 160 SIN MING DRIVE #05-10 SIN MING

AUTOCARE Singapore 575722

Singapore 5/5/22

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2021)

Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN7543M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

NO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Distorted / Cracked	972.10 FL	*762.70 FL
2	1		*FRONT BUMPER RETAINER	Necessary	50.90 FL	*50.90 FL
3	1		*FRONT BUMPER BEAM	Repair	460.10 FL	*- FL
4	1		*FRONT BUMPER SPORT LAMP	Serviceable	38.10 FL	*- FL
5	8		*FRONT BUMPER CLIPS	Necessary	46.40 FL	*46.40 FL
6	1		*FRONT HEAD LAMP	Cut	1,909.40 FL	*1,820.20 FL
7	1		*FRONT HEAD LAMP LOWER GARNISH	Serviceable	64.70 FL	*- FL
8	1		*FRONT FENDER (LOCAL REPAIR)	Dented	544.24 FS	*120.00 FS
9	1		*FRONT FENDER PROTECTOR	Dented / Cut	195.10 FL	*195.10 FL
10	1		*FRONT FENDER SPLASH SHIELD	Serviceable	150.00 FL	*- FL
11	10		*FRONT SPLASH SHIELD CLIPS	Necessary	58.00 FL	*58.00 FL
12	1		*FRONT TYRE (60%)	Cut	250.00 FS	*150.00 FS
F=Fra	nchise	part. S=SpcN	Nett. L=ListItemDisc.			
				Sub Total (S\$)	4,739.04	3,203.30
			- List Item Discou	nt on L Items 20.00/20.00% (S\$)	788.96	586.66

Report was unsubmitted during this print-out.

**Total Parts (S\$)** 

3,950.08

2,616.64

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	60.00	20.00
2	TO CHECK WHEEL ALIGNMENT COMPUTERISE	New	80.00	60.00
3	RENEW THE ABOVE MENTIONED PARTS KNOCKING, CUTTING, WELDING & STRAIGHTEN FRONT DAMAGED PARTS	New	700.00	480.00
4	SPRAY PAINTING	New	700.00	580.00
	Gross Labour Cost (S\$)		1,540.00	1,140.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >