



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2108692

INV Date 17/12/2021

Reference CC4/LPC21009667/Krs3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SLA 3447C  
Insured Veh. GBC 7875G  
Claim No. 202121VC00/024951  
Policy No. Z/20/VC00/109208  
Accident Date 10/09/2021  
Inspection Date 15/09/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21009667/Krs3q2 Date: 17/12/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBC 7875G	Veh. Inspected	SLA 3447C
	Policy No.	Z/20/VC00/109208	Coverage (\$)	0.00
	Claim No.	202121VC00/024951	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	15/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W.318I (A)	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WBA8E32040K497929	Colour	METALLIC GREY
	Odometer	104768 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R16	PIRELLI	8 mm
	L/H Rear Tyre	215/60 R16	PIRELLI	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	10/09/2021	Inspection Date	15/09/2021
	Survey held at	CARIS AUTOWORKS PRIVATE LIMITED 160 SIN MING DRIVE, #05-03, SIN MING AUTOCITY, SINGAPORE 575722		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 3447C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER (FRONT)	BUCKLED / CRACKED	1,538.15	1,392.42
1	BUMPER TOWING COVER (FRONT RIGHT)	SERVICEABLE	59.64	-
1	BUMPER LAMP COVER (FRONT RIGHT)	DISTORTED / CRACKED	110.59	110.59
1	HEADLAMP (FRONT RIGHT)	CRACKED	3,088.16	3,068.40
	LESS 10% DISCOUNT		-479.65	-457.14
			4,316.89	4,114.27
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BODY CLIPS (SN)	NECESSARY	100.00	50.00
			100.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL KNOCKING .		800.00	250.00
	SPRAY PAINTING.		600.00	250.00
			1,400.00	500.00
	<b>GRAND TOTAL</b>		<b>5,816.89</b>	<b>4,664.27</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,700.00</b>

Report Ref No. CC4/LPC21009667/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLA 3447C

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

