

Wm Pm
L/S
My 11L sy
3 dys

Ms China Taiping Insurance (Singapore) Pte Ltd
 Date 14/9/2021
 Attn : MOTOR CLAIMS DEPT

Steve (LKK)
16/9/21, 11.00am

ESTIMATE

VEHICLE NO. SLJ573T
 CHASSIS NO : GP71043105
 MAKE / MODEL : Honda Shuttle Hybrid 1.5 CVT
 DATE OF ACCIDENT : 03/07/2021
 YOUR INSURED VEHICLE NUMBER : SJC2801G
 MILEAGE : 381058 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front bumper <i>BR</i>	1PC	\$ 1,350.00	\$ 1,350.00
2	Front bumper reinforcement <i>?</i>	1PC	\$ 660.00	\$ 660.00
3	Front bumper RH tow cover <i>CRU</i>	1PC	\$ 54.00	\$ 54.00
4	Front bumper RH side retainer <i>BR</i>	1PC	\$ 21.00	\$ 21.00
5	Front bumper lower grille <i>?</i>	1PC	\$ 294.00	\$ 294.00
LIST TOTAL S\$:				\$ 2,379.00
20.00% DISCOUNT S\$:				\$ 475.80
				\$ 1,903.20

<u>SPECIAL NETT</u>			
3	Bumper clips <i>mic</i>	1 SET	\$ 80.00 <i>30</i>
Special Nett Total S\$:			\$ 80.00

<u>LABOUR CHARGES</u>			
1	TO REMOVE FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.		\$ 600.00 <i>230</i>

2	TO RESPRAY FRONT BUMPER		\$ 400.00 <i>200</i>
---	-------------------------	--	----------------------

LABOUR TOTAL S\$:	\$ 1,000.00
TOTAL S\$:	\$ 2,903.20
7% GST	\$ 203.22
GRAND TOTAL S\$:	\$ 3,106.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification is allowed
- Supplemental items to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: