

*Wm Pm*  
*L/S*  
*My 11 L sy*  
*3 dys*

Ms China Taiping Insurance (Singapore) Pte Ltd  
 Date 14/9/2021  
 Attn : MOTOR CLAIMS DEPT

*Steve (LKK)*  
*16/9/21, 11.00am*

**ESTIMATE**

VEHICLE NO. SLJ573T  
 CHASSIS NO : GP71043105  
 MAKE / MODEL : Honda Shuttle Hybrid 1.5 CVT  
 DATE OF ACCIDENT : 03/07/2021  
 YOUR INSURED VEHICLE NUMBER : SJC2801G  
 MILEAGE : 381058 km

PARTS DESCRIPTION	
1	Front bumper <i>BR</i>
2	Front bumper reinforcement <i>DD</i>
3	Front bumper RH tow cover <i>CRU</i>
4	Front bumper RH side retainer <i>BR</i>
5	Front bumper lower grille <i>x nn</i>

QTY	UNIT PRICE	LIST PRICE
1PC	\$ 1,350.00	\$ 1,350.00
1PC	\$ 660.00	\$ 660.00
1PC	\$ 54.00	\$ 54.00
1PC	\$ 21.00	\$ 21.00
1PC	\$ 294.00	\$ 294.00
LIST TOTAL S\$:		\$ 2,379.00
20.00% DISCOUNT S\$:		\$ 475.80
		\$ 1,903.20

*2085*  
*-20%*  
*1668*

**SPECIAL NETT**

3 Bumper clips *mic*

1 SET	\$ 80.00
Special Nett Total S\$:	\$ 80.00

*30*

**LABOUR CHARGES**

1 TO REMOVE FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.

\$ 600.00 *230*

2 TO RESPRAY FRONT BUMPER

\$ 400.00 *200*

LABOUR TOTAL S\$:	\$ 1,000.00
TOTAL S\$:	\$ 2,903.20
7% GST	\$ 203.22
GRAND TOTAL S\$:	\$ 3,106.42

*2128*  
*L/S - 1702.40*  
*= 1700*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification is allowed
- Supplemental items to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: