



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA21009674/T1vf3e2	Date: 22/10/2021
			Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9162L	Veh. Inspected	SMA 4248S	
Policy No.	BVFCB0013842100	Coverage (\$)	0.00	
Claim No.	NSV2100120/SG	Excess (\$)	0.00	
Assign From	STELLA GOH	Assign Date	15/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GK81201409	Colour	GREY	
Odometer	83320 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	285/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	285/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	285/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	285/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/09/2021	Inspection Date	16/09/2021	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	