

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: SMP818U
Make and model: Honda Shuttle
Chassis: GP72004610

Qty	Spare parts	List price	2019
1	Tailgate	\$	✓ 1,193.00 DD✓
1	Tailgate windscreen glass rubber moulding	\$	108.20 145.60 NEC✓
1	Tailgate windscreen glass wiper motor	\$	390.40 NDX
1	Tailgate RH lamp	\$	574.00 642.00 } BR✓
1	Tailgate LH lamp	\$	574.00 642.00 } BR✓
1	Tailgate outer garnish	\$	298.50 383.10 BR✓
1	Tailgate outer garnish centre emblem	\$	✓ 38.00 } NEC✓
1	Tailgate "Shuttle" emblem	\$	✓ 55.00 } NEC✓
1	Tailgate "Hybrid" emblem	\$	45.00 75.80 } NDX
1	Tailgate RH number plate lamp	\$	25.80 } NDX
1	Tailgate LH number plate lamp	\$	25.80 } NDX
1	Tailgate RH absorber damper ✗	\$	✓ 165.00 } BT✓
1	Tailgate LH absorber damper ✗	\$	✓ 165.00 } BT✓
1	Tailgate RH hinge	\$	52.00 } NDX
1	Tailgate LH hinge	\$	52.00 } NDX
1	Tailgate inner pull handle ✗	\$	✓ 26.00 BR✓
1	Tailgate inner trim board	\$	✓ 321.00 BR✓
1	Tailgate inner mechanism lock	\$	126.50 157.30 JM✓
1	Tailgate inner mechanism lock catch	\$	✓ 27.50 BT✓
1	Tailgate outer lock opener switch	\$	✓ 175.50 SC✓
1	Tailgate RH lamp	\$	✓ 395.00 BR✓
1	Tailgate RH lamp inner sponge gasket	\$	✓ 32.00 NEC✓
1	Tailgate LH lamp	\$	✓ 395.00 BR✓
1	Tailgate LH lamp inner sponge gasket	\$	✓ 32.00 NEC✓
1	Tailgate weatherstrip	\$	115.60 168.50 TN✓
1	Rear bumper	\$	936.50 1,355.60 BR✓
1	Rear bumper RH reflector garnish	\$	✓ 45.00 } BR
1	Rear bumper RH reflector	\$	✓ 45.00 } BR
1	Rear bumper LH reflector garnish	\$	✓ 45.00 BR✓
1	Rear bumper LH reflector	\$	✓ 45.00 BR✓
1	Rear bumper RH side retainer	\$	✓ 26.50 } NEC✓
1	Rear bumper LH side retainer	\$	✓ 26.50 } NEC✓
1	Rear bumper RH inner sponge	\$	✓ 89.50 } BR✓
1	Rear bumper LH inner sponge	\$	✓ 89.50 } BR✓
1	Rear bumper towing cover	\$	✓ 16.80 MIS✓
1	Rear bumper RH under cover	\$	98.30 } NDX
1	Rear bumper LH under cover	\$	98.30 } NDX

1	End panel	\$	✓ 560.80	DDV
1	End panel inner garnish	\$	✓ 155.50	BRV
1	End panel buzzer sensor	\$	✓ 87.00	? BRV
1	End panel antenna sensor	\$	86.00	? NDX
1	Rear RH fender ✕	\$	✓ 1,010.90	DDV
1	Rear RH fender glass with rubber moulding ✕	\$	✓ 578.60	NEV
1	Rear RH fender splash shield	\$	53.70	? NDX
1	Rear RH fender inner trim board	\$	455.60	489.90 ? BRV
1	Rear RH fender	\$	1,010.90	} RPTX
1	Rear RH fender glass with rubber moulding	\$	578.60	
1	Rear RH fender splash shield	\$	53.70	
1	Rear RH fender inner trim board ✕ <i>repair</i>	\$	✓ 489.90	? BRV
1	Floor panel	\$	✓ 1,180.00	? DDV
1	Floor panel compartment tray box	\$	✓ 420.80	? DDV
1	Floor panel compartment tray box cover	\$	261.00	295.00 ? BRV
1	Floor panel top cover board	\$	585.00	? NDX
1	RH taillamp	\$	✓ 520.50	BRV
1	RH taillamp inner sponge gasket	\$	✓ 32.00	NEV
1	RH taillamp panel	\$	166.70	? NDX
1	RH taillamp lower extension panel	\$	194.30	? NDX
1	LH taillamp	\$	✓ 520.50	BRV
1	LH taillamp inner sponge gasket	\$	✓ 32.00	NEV
1	LH taillamp panel	\$	166.70	? NDX
1	LH taillamp lower extension panel	\$	194.30	? NDX
1	Exhaust silencer	\$	756.00	} ? NDX
1	Exhaust silencer heat shield	\$	78.60	
1	Bonnet ✕	\$	920.80	1,258.40 DDV
1	Front bumper	\$	✓ 1,050.60	DDV
1	Front bumper RH side retainer	\$	✓ 15.40	} NEV
1	Front bumper LH side retainer	\$	✓ 15.40	
1	Front bumper reinforcement	\$	✓ 387.60	? DDV
1	Front bumper RH fog lamp cover ✕	\$	✓ 33.20	} BRV
1	Front bumper RH fog lamp cover garnish ✕	\$	✓ 18.80	
1	Front bumper LH fog lamp cover ✕	\$	✓ 33.20	
1	Front bumper LH fog lamp cover garnish ✕	\$	✓ 18.80	
1	Front bumper lower grille	\$	✓ 145.30	BRV
1	RH headlamp	\$	950.00	2,250.00 ? BRV
1	RH headlamp lower bracket ✕	\$	✓ 45.00	? BRV
1	LH headlamp	\$	950.00	2,250.00 ? BRV
1	LH headlamp lower bracket ✕	\$	✓ 45.00	? BRV
1	Front grille	\$	✓ 395.00	BRV
1	Front grille emblem	\$	✓ 45.20	NEV
1	Support panel ✕	\$	749.20	780.40 ? DDV
1	Support panel top garnish ✕	\$	62.30	NDX
1	Aircon condenser	\$	1,203.70	NDX
1	Radiator	\$	1,847.30	NDX
1	Radiator RH air guide	\$	79.80	NDX
1	Radiator LH aid guide	\$	79.80	NDX

\$	30,121.40
-20% \$	6,024.28
\$	24,097.12

Qty Spare parts

Special Nett price

- 1 Tailgate windscreen glass sealant
- 1 Tailgate windscreen glass inner seal
- 1 Tailgate inner trim board clips (set)
- 1 Tailgate reverse camera
- 1 Rear bumper clips (set)
- 1 Rear bumper reverse sensors (set)
- 1 Rear RH fender inner trim board clips (set)
- 1 Rear RH fender joint sealant
- 1 Rear LH fender inner trim board clips (set)
- 1 Rear LH fender joint sealant
- 1 End panel joint sealant
- 1 LH taillamp lower extension panel joint sealant
- 1 RH taillamp lower extension panel joint sealant
- 1 Floor panel joint sealant
- 1 Front bumper clips (set)
- 1 Front grille clips (set)
- 1 Support panel top cover clips (set)
- 1 Radiator coolant

\$	30.00	70.00	NECV
\$	30.00	50.00	NECV
\$	30.00	70.00	NECV
\$		650.00	? NDX
\$	30.00	70.00	NECV
\$	200.00	280.00	SCV
\$	30.00	70.00	NECV
\$		70.00	NNX
\$		70.00	NNX
\$	30.00	70.00	NECV
\$		45.00	? NNX
\$		45.00	NNX
\$	40.00	70.00	NECV
\$	30.00	70.00	NECV
\$	30.00	50.00	NECV
\$		60.00	? NNX
\$		55.00	NNX

Labour and painting

(REAR PORTION)

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

Spray painting on affected panels

Check wiring and lighting system

Apply rust coating chemical on affected panels

Remove and reinstall tailgate windscreen glass to assist repair

Remove and replace tailgate inner mechanism to new tailgate

Remove and replace tailgate reverse camera to assist repair

Remove and replace rear inner trims, garnish, boards, seats, roof lining and carpet to assist repair

\$	1800.00	2,200.00	✓
\$	800.00	1,800.00	✓
\$	80.00	120.00	✓
\$	80.00	150.00	✓
\$	120.00	200.00	✓
\$	80.00	120.00	✓
\$		100.00	NNX
\$	80.00	320.00	✓

Remove and replace rear bumper reverse sensors to assist repair	\$ 600.00	100.00 ✓
Conduct, repair and straighten rear chassis members on chassis alignment bench	\$	400.00 NNX
(FRONT PORTION)		
Labour charges to remove, check, replace and reinstall damaged bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 600.00	1,000.00 ✓
Spray painting on affected panels	\$ 400.00	1,000.00 ✓
Check wiring and lighting system	\$	80.00 NNX
Apply rust coating chemical on affected panels	\$	40.00 NNX
Remove and replace aircon condenser, pipes and hoses to assist repair To refill aircon gas	\$	220.00 NNX
Remove and replace radiator assy, hoses and fan assy to assist repair To refill coolant	\$	220.00 NNX

Survey Resurvey
 21/9/2021 27/9/2021
 1810 hrs 1455 hrs
 T. Lim T. Lim
 [Signature] [Signature]

Total: \$ 34,102.12

Parts 14,680.56
 SH 480.00
 Labour 4,100.00

 19,260.56
 @20% 3,852.11

 15,408.45

Lump sum repair
 Repair days 16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 15,400/2

T. Lim
 21/12/2021