

SJU27146. 2009 Nov

Mazda 3 1598 cc

TP China

Denise

JM6BL10ZIA0117827

Rear Number Plate	2	30(SN)	X
Rear Number Plate Holder	44 m	30(SN)	X
Rear Bumper Distorted		106130	/
Rear Bumper Clips. New		30(SN)	/
Rear Bumper Side Holder x 2	RH Rnd	46.5 x 2 = 93	46.50
Rear Bumper Reinforcement	Dented	529.60	/
Rear Bumper Reflector RH.	crushed	59.20	/
Reverse Sensor	Damaged	280(SN) 28(SN)	<u>20(SN)</u>
Rear End Panel	Dented	435.70	/
Rear End Panel Top Garnish	new	203.40	X
Rear End Panel Sealant	new	<u>60(SN)</u>	/
Taillamp RH	crushed	981.30	/
Taillamp Panel RH.	Reis	328.40	X.

SJU2714G.

Panel Beating

~~800~~ 600

Spray Painting.

~~800~~ 500.

Wiring.

~~50~~ 30

To spray tuff coat

~~150~~ 60

To remove reverse sensor

~~100~~ 50

To remove upholstery

~~150~~ 60.

list: 3113.60

Labour: 1300

len 20%: 2490.88

total: 4080.88

S.N: 290

f/s: 3250 ✓

05 hrs.

6125.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: