

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2109-194

DATE : 15-Sep-2021

POLICY NO. : P10549179R00

VEHICLE REG. NO. : SLZ9577P

VEHICLE MAKE : SUBARU FORESTER 2.0I-L CVT AWD

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 800.00	\$ 800.00
2	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
3	Rear Bumper Retainer LH	1	\$ 30.00	\$ 30.00
4	Rear Bumper Bracket Corner LH	1	\$ 30.00	\$ 30.00
5	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
6	Rear Bumper Tow Eye Cover	1	\$ 30.00	\$ 30.00
7	Rear Tail Lamp LH	1	\$ 550.00	\$ 550.00
8	Rear Tail Lamp RH	1	\$ 550.00	\$ 550.00
9	Rear Tailgate Door	1	\$ 1,280.00	\$ 1,280.00
10	Rear Tailgate Door Lock	1	\$ 250.00	\$ 250.00
11	Rear Tailgate Door Lock Latch	1	\$ 40.00	\$ 40.00
12	Rear Tailgate Door Rubber Seal	1	\$ 180.00	\$ 180.00
13	Rear Tailgate Door Inner Trim	1	\$ 230.00	\$ 230.00
14	Rear Subaru Logo Emblem	1	\$ 100.00	\$ 100.00
15	Rear Subaru Emblem	1	\$ 100.00	\$ 100.00
16	Rear Forester Emblem	1	\$ 100.00	\$ 100.00
17	Rear AWD Emblem	1	\$ 100.00	\$ 100.00
18	Rear Bumper Reflector LH	1	\$ 50.00	\$ 50.00
19	Rear Bumper Reflector RH	1	\$ 50.00	\$ 50.00
20	Rear Reinforcement	1	\$ 480.00	\$ 480.00
21	Rear / End Panel Garnish	1	\$ 90.00	\$ 90.00
22	End Panel	1	\$ 450.00	\$ 450.00
23	Rear Windscreen Molding	1	\$ 90.00	\$ 90.00
24	Rear Floor Pan Panel	1	\$ 550.00	\$ 550.00
Total Spare Parts				\$ 6,210.00
	<u>SPECIAL NETT</u>			
25	Rear License Plate with Frame	1	\$ 40.00	\$ 40.00
26	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
27	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
	<u>LABOUR</u>			

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2109-194

DATE : 15-Sep-2021

POLICY NO. : P10549179R00

VEHICLE REG. NO. : SLZ9577P

VEHICLE MAKE : SUBARU FORESTER 2.0I-L CVT AWD

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Spray Painting Rear Bumper, Tailgate, Inner Panel, Floor Panel and Inner Panel include Blending	1	\$ 800.00	\$ 800.00
29	Repair and Replace Affected Accident Parts	1	\$ 800.00	\$ 800.00
30	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
31	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
32	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 150.00
33	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
34	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Total Labour	\$ 2,040.00
Amount Before Excess	\$ 8,530.00
Add GST @ 7%	597.10
Total Amount Payable	\$ 9,127.10