

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2109-194
DATE : 15-Sep-2021
POLICY NO. : P10549179R00
VEHICLE REG. NO. : SLZ9577P
VEHICLE MAKE : SUBARU FORESTER 2.0I-L CVT AWD

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de / A</i>	1	\$ 800.00	\$ 800.00
2	Rear Bumper Retainer RH <i>X</i>	1	\$ 30.00	\$ 30.00
3	Rear Bumper Retainer LH <i>?</i>	1	\$ 30.00	\$ 30.00
4	Rear Bumper Bracket Corner LH <i>?</i>	1	\$ 30.00	\$ 30.00
5	Rear Bumper Clip <i>ne /</i>	10	\$ 5.00	\$ 50.00
6	Rear Bumper Tow Eye Cover <i>X</i>	1	\$ 30.00	\$ 30.00
7	Rear Tail Lamp LH <i>2ra /</i>	1	\$ 550.00	\$ 550.00
8	Rear Tail Lamp RH <i>X</i>	1	\$ 550.00	\$ 550.00
9	Rear Tailgate Door <i>st /</i>	1	\$ 1,280.00	\$ 1,280.00
10	Rear Tailgate Door Lock <i>st /</i>	1	\$ 250.00	\$ 250.00
11	Rear Tailgate Door Lock Latch <i>X</i>	1	\$ 40.00	\$ 40.00
12	Rear Tailgate Door Rubber Seal <i>ne /</i>	1	\$ 180.00	\$ 180.00
13	Rear Tailgate Door Inner Trim <i>?</i>	1	\$ 230.00	\$ 230.00
14	Rear Subaru Logo Emblem <i>ne /</i>	1	\$ 100.00	\$ 100.00
15	Rear Subaru Emblem <i>ne /</i>	1	\$ 100.00	\$ 100.00
16	Rear Forester Emblem <i>ne /</i>	1	\$ 100.00	\$ 100.00
17	Rear AWD Emblem <i>ne /</i>	1	\$ 100.00	\$ 100.00
18	Rear Bumper Reflector LH <i>?</i>	1	\$ 50.00	\$ 50.00
19	Rear Bumper Reflector LH <i>X</i>	1	\$ 50.00	\$ 50.00
20	Rear Reinforcement <i>st /</i>	1	\$ 480.00	\$ 480.00
21	Rear / End Panel Garnish <i>?</i>	1	\$ 90.00	\$ 90.00
22	End Panel <i>repair</i>	1	\$ 450.00	\$ 450.00
23	Rear Windscreen Molding <i>ne /</i>	1	\$ 90.00	\$ 90.00
24	Rear Floor Pan Panel <i>X</i>	1	\$ 550.00	\$ 550.00
Total Spare Parts				\$ 6,210.00
SPECIAL NETT				
25	Rear License Plate with Frame <i>X</i>	1	\$ 40.00	\$ 40.00 <i>X</i>
26	Rear Windscreen Sealant <i>ne /</i>	1	\$ 40.00	\$ 40.00 <i>X</i>
27	Reverse Sensor <i>ne /</i>	1	\$ 200.00	\$ 200.00 <i>X</i>
Total Special Nett				\$ 280.00
LABOUR				

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2109-194
DATE : 15-Sep-2021
POLICY NO. : P10549179R00
VEHICLE REG. NO. : SLZ9577P
VEHICLE MAKE : SUBARU FORESTER 2.0I-L CVT AWD

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Rasul / 5 days / 15/09/21
4p90010068 / L/S @ 1620
Resurvey after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Spray Painting Rear Bumper, Tailgate, Inner Panel, Floor Panel and Inner Panel include Blending	1	\$ 800.00	\$ 800.00
29	Repair and Replace Affected Accident Parts	1	\$ 800.00	\$ 800.00
30	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
31	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
32	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 150.00
33	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
34	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,040.00
Amount Before Excess				\$ 8,530.00
Add GST @ 7%				597.10
Total Amount Payable				\$ 9,127.10

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: