



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21009685/Buf3e2	
			Date: 04/10/2021	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SM 72Z	Veh. Inspected	SLR 7845X	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D13722109	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	15/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR HYBRID 1.8	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102056855	Colour	BLUE	
Odometer	215163 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	TOURADOR	5 mm	
L/H Front Tyre	225/55 R17	TOURADOR	5 mm	
R/H Rear Tyre	225/55 R17	TRIANGLE	5 mm	
L/H Rear Tyre	225/55 R17	TRIANGLE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/09/2021	Inspection Date	16/09/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	