



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PH 6868S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	BROKEN		
	FRONT LHS MIRROR		135.00	135.00
	LESS 10% DISCOUNT		-	-13.50
			135.00	121.50
	<u>LABOUR</u>			
	TO REMOVE DAMAGED PARTS AND INSTALL FRONT LHS MIRROR.		80.00	50.00
			80.00	50.00
GRAND TOTAL			215.00	171.50
RECOMMENDED COST OF REPAIRS				171.50

Report Ref No. CS/SMR21009688/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.