



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0765/2021/ZK
DATE : 14-Sep-21
WIP : 44216

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ADLI LIM @ADLI BIN ADAM
ADDRESS : 1043 UPPER CHANGI ROAD NORTH
SINGAPORE 507678
TELEPHONE : HP +65 92325934
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900170399-02
VEHICLE NO : **SLT 8279 M**
MODEL CODE : A4 SEDAN 2.0 TFSI
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 084456
CHASSIS NO : WAUZZZF4XKA089565
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-21
PLACE OF ACCIDENT : UPPER CHANGI ROAD EAST AT THE JUNCTION OF SIMEI ROAD /SOMAPAH ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 8279 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND BONNET	\$	2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,122.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8279 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rehd</i>	1	\$ 1,787.00	✓	
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 587.00	+	
3	FRONT BUMPER SECURING STRIP <i>Neu</i>	2	\$ 71.00	+	
4	FRONT BUMPER GRILLE <i>Neu</i>	1	\$ 196.00	+	
5	FRONT BUMPER CLOSING ELEMENT <i>Neu</i>	1	\$ 210.00	+	
6	RADIATOR AIR GUIDE - LH / RH <i>Neu</i>	2	\$ 126.00	+	
7	RADIATOR GRILLE <i>Rehd</i>	1	\$ 2,184.00	✓	
8	AIR GUIDE GRILLE - RH ?	1	\$ 365.00	?	
9	FRONT BUMPER REINFORCEMENT FOAM PIECE ?	1	\$ 124.00	?	
10	FRONT BUMPER REINFORCEMENT BAR ?	1	\$ 845.00	?	
11	FRONT BUMPER TOP COVER ?	1	\$ 127.00	?	
12	CAUTION STICKER ?	1	\$ 14.00	?	
13	AIR CONDITIONER STICKER ?	1	\$ 8.00	?	
14	FRONT BUMPER BRACKET ?	1	\$ 137.00	?	
15	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 58.00	?	
16	POP RIVET <i>Neu ?</i>	4	\$ 4.00	?	
17	HORN - RH <i>Neu</i>	1	\$ 126.00	+	
18	HORN BRACKET - RH <i>Neu</i>	1	\$ 29.00	+	
19	FRONT PARKING AID SENSOR <i>3 MP</i>	2	TBC	+	
20	FRONT PARKING AID SENSOR SEAL <i>MP</i>	4	\$ 14.00	+	
SUB TOTAL SPARE PARTS		:	\$ 7,012.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8279 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BONNET <i>Dented</i>	1	\$ 3,246.00	✓	
22	FRONT BONNET ATTACHMENT PART <i>see m</i>	1	\$ 412.00	+	
23	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER <i>m</i>	3	\$ 84.00	✓	
24	FRONT BONNET RELEASE CABLE	1	\$ 58.00	+	
25	FRONT BONNET HOOD RELEASE	1	\$ 14.00	+	
26	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	+	
27	FRONT BONNET CABLE COVER	1	\$ 10.00	+	
28	FRONT BONNET STRIKER	1	\$ 50.00	+	
29	FRONT BONNET LOCK	1	\$ 214.00	+	
30	FRONT HEADLIGHT - RH ?	1	\$ 7,693.00	?	
31	FRONT HEADLIGHT LIFT CYLINDER - RH <i>fail</i>	1	\$ 210.00	+	
32	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>n</i>	1	\$ 93.00	+	
33	RADIATOR AIR GUIDE - RH OUTER <i>2</i>	1	\$ 28.00	+	
34	RADIATOR AIR GUIDE - RH INNER <i>fail</i>	1	\$ 12.00	+	
35	RADIATOR AIR DUCT - RH UPPER <i>m</i>	1	\$ 16.00	+	
36	RADIATOR AIR DUCT - RH LOWER	1	\$ 22.00	+	
37	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓	
38	SUNDRIES ?		\$ 300.00	?	
TOTAL SPARE PARTS			\$ 19,592.00		
TOTAL LABOUR CHARGES			\$ 5,122.00		
GRAND TOTAL			\$ 24,714.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Li*
SURVEYED DATE : *15/09/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT