

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/CD/0765/2021/ZK

5-Oct-21

CHANG

1 of 1

SLT 8279 M

AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. TO CHECK ON ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	\$ 1,400.00	✓
2	TO REMOVE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET.	\$ 2,800.00	1250.
Parts			
1	OUTER TEMP. SENSOR BRACKET <i>Don't</i>	\$ 19.00	✓
2	RADIATOR AIR GUIDE - LH <i>for</i>	\$ 12.00	✓
3	FRONT REINFORCEMENT BEAM BRACKET - RH <i>Best</i>	\$ 228.00	✓
GRAND TOTAL		\$ 4,459.00	

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]



Authorised Signature

Car-in

4/10/21

wip: 44216

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Kiam /

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8279 M


Alfa - Action

- 4 days

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$	1,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	587.00	+
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$	71.00	+
4	FRONT BUMPER GRILLE <i>new</i>	1	\$	196.00	+
5	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$	210.00	+
6	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$	126.00	+
7	RADIATOR GRILLE <i>crushed</i>	1	\$	2,184.00	✓
8	AIR GUIDE GRILLE - RH ?	1	\$	365.00	?
9	FRONT BUMPER REINFORCEMENT FOAM PIECE <i>crushed</i>	1	\$	124.00	✓
10	FRONT BUMPER REINFORCEMENT BAR <i>crushed</i>	1	\$	845.00	✓
11	FRONT BUMPER TOP COVER ?	1	\$	127.00	?
12	CAUTION STICKER ?	1	\$	14.00	?
13	AIR CONDITIONER STICKER ?	1	\$	8.00	?
14	FRONT BUMPER BRACKET <i>and</i>	1	\$	137.00	✓
15	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$	58.00	✓
16	POP RIVET <i>new</i>	4	\$	4.00	✓
17	HORN - RH <i>new</i>	1	\$	126.00	+
18	HORN BRACKET - RH <i>new</i>	1	\$	29.00	+
19	FRONT PARKING AID SENSOR <i>3 MP</i>	2		TBC	+
20	FRONT PARKING AID SENSOR SEAL <i>new</i>	4	\$	14.00	+
SUB TOTAL SPARE PARTS		:	\$	7,012.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6641 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8279 M

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BONNET <i>Dented</i>	1	\$ 3,246.00	✓
22	FRONT BONNET ATTACHMENT PART <i>new</i>	1	\$ 412.00	✓
23	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER <i>new</i>	3	\$ 84.00	✓
24	FRONT BONNET RELEASE CABLE	1	\$ 58.00	✓
25	FRONT BONNET HOOD RELEASE	1	\$ 14.00	✓
26	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	✓
27	FRONT BONNET CABLE COVER	1	\$ 10.00	✓
28	FRONT BONNET STRIKER	1	\$ 50.00	✓
29	FRONT BONNET LOCK	1	\$ 214.00	✓
30	FRONT HEADLIGHT - RH <i>cracked</i>	1	\$ 7,693.00	✓
31	FRONT HEADLIGHT LIFT CYLINDER - RH <i>new</i>	1	\$ 210.00	✓
32	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>new</i>	1	\$ 93.00	✓
33	RADIATOR AIR GUIDE - RH OUTER <i>cracked</i>	1	\$ 28.00	✓
34	RADIATOR AIR GUIDE - RH INNER <i>cracked</i>	1	\$ 12.00	✓
35	RADIATOR AIR DUCT - RH UPPER <i>new</i>	1	\$ 16.00	✓
36	RADIATOR AIR DUCT - RH LOWER <i>new</i>	1	\$ 22.00	✓
37	FRONT NO PLATE <i>Painted</i>	S/N	\$ 60.00	✓
38	SUNDRIES		\$ 300.00	✓
TOTAL SPARE PARTS		:	\$ 19,592.00	
TOTAL LABOUR CHARGES		:	\$ 5,122.00	
GRAND TOTAL		:	\$ 24,714.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.