

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No: SLA3707C Yr Regn: 29/2/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

) _ \$ + RS _ \$

) Photos

) Others

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Hil: Jasper

4/5 @ 3500
 3 days

VEHICLE No: SLA 3707C

1PC	BOOTLID	R		\$2,028.32	X
1PC	BOOTLID REAR LOGO	rec		\$98.00	✓
1PC	REAR BUMPER	to be / de		\$2,241.25	✓
1PC	REAR BUMPER LOWER BLACK GARNISH	Dis	1628.11	\$688.21	✓
2PCS	REAR BUMPER SIDE HOLDERS @\$185.00	11	562.30	\$370.00	X
2PCS	REAR BUMPER PDC SENSORS @\$185.00	rec		\$370.00	X
1PC	REAR BUMPER LOWER SKIRTING PLATE	one	600.25	\$650.00	✓
1PC	REAR BUMPER TOP RETAINER	11		\$225.00	X
1PC	REAR BUMPER REINFORCEMENT	Benf	715.32	\$845.11	✓
1SET	REAR BUMPER CLIPS & RIVET	rec		\$60.00	✓
1PC	REAR END PANEL	R		\$980.00	X
				\$8,555.89	

(102)

TO CHECK WIRING
 TO DISMANTLE & REFIX REAR PDC SENSOR
 TO DISMANTLE & REFIX CUSHION UPHOLSTERY
 TO RESET & REPROGRAMME DIAGNOSIS SYSTEM
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

\$50.00 20
 \$80.00 60
 11 \$120.00 X
 \$180.00 100
 11 \$60.00 X
 \$800.00 400
 \$1,080.00 500
 \$10,925.89

not allowed
 2hr
 1/5 @ 3500
 16/9/21
 3 days

P-3663 98
 102
 P-329758
 L-1080
 4377.58
 292
 350~

LKIK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: